

Vehicle Record	Service Date Shop	Service Explanation	Price	Mileage
2001 CLK 430 CP	4/24/12 German Autc	A/C system recharge, grille clip, refrigerant, fluorescent leak die, A/C oil	248.77	159,551
VIN	4/3/12 German Autc	Checked coolant leak, coolant pressure tested, replaced failed radiator cap, topped off coolant level	50.71	157,595
Assembled 06/09/2000	2/3/12 German Autc	Oil change fs, Eng/tran mounts, resealed valve covers, repl breather hoses, repl leak trans electrical plug, trans fluid, repl shifter bushings	1659.04	152,914
Record Since 12/09/2009		oil filter, oil filter carrier, valve cover gasket(2), seal ring, sealant, oil cap (\$90.00 discount)		152,914
	3/21/14 MVD	Emissions OBD (PASS 2 yrs)	27.75	208,000
	4/11/12 MVD	Registration (1yr)	157.16	N/A
	1/26/13 Discount	Tire Bead Leak, Free flat repair	0	182,704
	3/21/14 Big O Tire	Mount and Balance (2) Yokohama S Drive (Tirerack) 275/30ZR/19	Tirerack: 434.10 Big O: 43.98	208,000
		Damaged Wheel (rear driver side), free repair offered and signed by manager	478.08	208,000
	12/8/12 Discount	Tire(2) Michelin Pilot Sport A/S Plus 225/45ZR/17	498.34	178,009
	3/22/14 Halvoline	Oil change, oil filter (8.5qts Full Synthetic 5W30)	15.00 Discount	207,815
	10/12/12 Halvoline	Oil change, oil filter (8.5qts Full Synthetic 5W30)	10.00 Discount (Manager)	173,548
	11/30/13 Jiffy Lube	Oil change, oil filter (8.5qts Full Synthetic 5W30)	129	202,848
	4/29/13 German Autc	Repl rear brakes, resealed rear diff (new rear rotors, pads, sensor, diff seal (input/output), diff oil, engine sealer)	1171.54	189,306
	1/8/14 German Autc	Replaced front lower ball joints	394.29	205,537
	6/4/13 German Autc	Replaced serpentine belt, cleaned burned old belt, cleaned pulleys, (2) tires mounted 245/40ZR/17, A/C service	465.4	192,004
		Tirerack: 201.49	201.49	192,004
	5/18/13 Halvoline	Oil change, oil filter (8.5 qts Full Synthetic 5W30)	15.00 Discount	191,325
	3/23/13 Discount	Tire (1) 245/40R/17 Kumho Ecsta ASX (Due to flat rear passenger tire)	168.9	N/A
	2/18/13 Discount	Tire (1) Tire leak due to front left cracked rim (old age, not due to impact), spare wheel was mounted in its place	0	184,744
	2/8/13 Halvoline	Oil change, oil filter (8.5 qts Full Synthetic 5W30)	10.00 Discount (Manager)	183,760
	12/8/12 Halvoline	Oil change, oil filter (8.5 qts Full Synthetic 5W30)	15.00 Discount	178,012
	11/8/13 European Au	Radiator hose replacement, coolant, pressure test	285.52	201,322
	6/25/13 German Autc	Install Eibach Pro Kit lowering springs, wheel alignment	490	194,334
	7/28/11 Jiffy Lube	Oil change, oil filter (8.5 qts Full Synthetic 5W30)	104.21	136,002
	4/16/13 MVD	Registration (1yr)	145.26	N/A
	7/29/13 Halvoline	Oil change, oil filter (8.5 qts Full Synthetic 5W30)	3.00 Discount	196,299
	7/9/12 Halvoline	Oil change, oil filter (8.5 qts Full Synthetic 5W30)	10.00 Discount (Manager)	164,301
	12/22/09 German Autc	Battery Replacement	225.98	119,098
	12/9/09 German Autc	Oil change, oil filter (8.5 qts Full Synthetic 5W30), brake flush, coolant flush, front brake pads/rotors/wear sensors/wheel seals, instrument cluster	2045.34	118,478
		Repl SRS warning lamp, repl roof antenna cap, repl side marker lamps, exhaust rattle traced to loose heat shield (resecured)		118,478
	6/25/11 Discount	Tire(2) 245/40ZR/17 Michelin Pilot Sport A/S Plus	547.45	133,529
	4/4/11 MVD	Registration (1yr)	0	N/A
	3/5/12 MVD	Emissions OBD (PASS)	27.75	156,000
	3/15/12 Halvoline	Oil change, oil filter (8.5 qts Full Synthetic 5W30)	10.00 Discount (Manager)	156,171
	12/27/11 Halvoline	Oil change, oil filter (8.5 qts Full Synthetic 5W30)	8.00 Discount (Manager)	149,917
	11/16/11 German Autc	Vibration inspection at 45-55 mph after previous brake replacement (found need of front tire replacement, front ball joints, LCA and bushings, align	0	145,903
		Lower Control Arm bushings and alignment (837.00), shifter bushings (105.00), rear flex disc (419.00)	1361	145,903
	11/11/11 German Autc	Full brake pad and rotor replacement (front and rear)	848.76	145,324
	11/17/11 Discount	Tire (2) 245/40ZR/17 Michelin Pilot Sport A/S Plus	509.27	145,925
	7/21/11 Mercedes-Be	Headlight washer cover (1)	58	N/A
	7/6/12 Discount	Tire (2) 245/40ZR/17 Michelin Pilot Sport A/S Plus	524.57	163,703
	10/14/13 European Au	Replaced dead battery due to battery being connected during radiator replacement	300.58	200,357
			<b>Service Total:</b>	<b>12685.62</b>
<b>AutohausAZ Parts:</b>	Radiator, radiator drain plug, antenna seal/gasket kit, steering damper		312.74	
	Idler Pulley, Serpentine belt		65.53	
	Rear turn signal bulbs		17.14	
	H6W city headlight bulb		13.88	
	Wheel lugs		13.67	
			<b>AutohausAZ Total:</b>	<b>422.96</b>
<b>Modifications:</b>	H&R 15mm Spacer		123.98	
	LED Tail Lights		125	
	Brabus Monoblock VI Wheels		900	
	AMG Airbox		333	
	Eibach Pro Kit Lowering Springs		299.31	
	Exhaust Work		450	
	G2 Caliper Paint		55.7	
	K&N Air Filters		113.65	
	LED Door Sill Lights		15.99	
	JDM Toy Yellow Fog Lights (4)		41.64	
	Koni Sport Shocks		414.72	
	Ksport Kontrol Pro Coilovers		966	
			<b>Modification Total:</b>	<b>3838.99</b>
			<b>TOTAL SPENT ON VEHICLE:</b>	<b>16947.57</b>
<b>Future Mods:</b>	Projector Headlights	508.99	<b>Future Mod Total:</b>	<b>4347.98</b>

Service + AutohausAZ: 13108.58