

Mitchell Service: 910009

Description: 2007 Mercedes-Benz CLK550
 Body Style: 2D Conv Drive Train: 5.5L Inj 8 Cyl 7A RWD
 VIN: WDBTK72FX7F221855
 OEM/ALT: O Search Code: None
 Options: POWER DRIVER SEAT, POWER LOCK, POWER WINDOW, CRUISE CONTROL
 TILT STEERING COLUMN, POWER PASSENGER SEAT, TELESCOPIC STEERING COLUMN
 ANTI-LOCK BRAKE SYS., TRACTION CONTROL, SAFETY ROLLBAR, ALUM/ALLOY WHEELS
 LEATHER STEERING WHEEL, FRONT AIR DAM, REAR AIR DAM, TINTED GLASS
 GENUINE WOOD TRIM, AUTO AIR CONDITION, TRIP COMPUTER
 WIND DEFLECTOR OR BUFFER FOR CONVERTIBLE, SUBWOOFER, TELEMATIC SYSTEMS
 UNIVERSAL GARAGE DOOR OPENER, VARIABLE ASSISTED STEERING, ANTI-THEFT SYSTEM
 AUTOMATIC HEADLIGHTS, INTERIOR AUTOMATIC DAY/NIGHT OR ELECTROCHROMATIC MIRROR
 VEHICLE THEFT TRACKING/NOTIFICATION, DAYTIME RUNNING LIGHTS
 AM/FM STEREO CD/MP3 PLAYER, ELECTRONIC STABILITY CONTROL
 EXTERIOR MEMORY MIRRORS, KEYLESS ENTRY SYSTEM, POWER DISC BRAKES
 POWER HEATED ELECTROCHROMATIC EXTERIOR MIRRORS, POWER LIFTGATE\TRUNK
 RAIN SENSING WIPERS, REAR SPOILER, STEERING WHEEL AUDIO CONTROLS

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	006870	REF	REFINISH	R Frt Flap			C 0.3
2	006871	REF	REFINISH	L Frt Flap			C 0.3
3	005012	REF	REFINISH	R Frt Washer Nozzle Cover			C 0.3
4	005013	REF	REFINISH	L Frt Washer Nozzle Cover			C 0.3
5	005016	REF	REFINISH	Frnt Tow Hook Cover			C 0.3
6	AUTO	BDY	OVERHAUL	Frnt Bumper Cover Assy			3.0 #
7	005022	BDY	REMOVE/REPLACE	Frnt Bumper Cover	209 885 52 25	0.00	* INC #
8	AUTO	REF	REFINISH	Frnt Bumper Cover			C 2.5
9	AUTO	BDY	REMOVE/REPLACE	Frnt Add w/Headlamp Washers			0.5
10	AUTO	BDY	REMOVE/REPLACE	Frnt Add w/Parking Sensor			0.9 #
11	AUTO	BDY	CHECK/ADJUST	Fog Lamps			0.4
12	005026	BDY	REMOVE/REPLACE	Frnt Ctr Bumper Cover Grille	209 885 06 53	288.00	* INC
13	005027	BDY	REMOVE/REPLACE	R Frnt Otr Bumper Grille	209 885 08 53	117.00	INC
14	005028	BDY	REMOVE/REPLACE	L Frnt Otr Bumper Grille	209 885 07 53	117.00	INC
15	005030	BDY	REMOVE/REPLACE	R Frnt Bumper Cover Moulding	209 885 10 21	43.50	INC #
16	005031	BDY	REMOVE/REPLACE	L Frnt Bumper Cover Moulding	209 885 09 21	43.50	INC #
17	900500	BDY *	REMOVE/REPLACE	R Frnt Bumper Joint Cover	209 885 02 22	7.00	* 0.0*
18	900500	BDY *	REMOVE/REPLACE	L Frnt Bumper Joint Cover	209 885 01 22	7.00	* 0.0*
19	900500	BDY *	REMOVE/REPLACE	Frnt Bumper Absorber	209 885 00 16	23.50	* 0.0*
20	005048	BDY	REMOVE/REPLACE	R Frnt Bumper Reinforcement	209 885 06 16	13.50	INC
21	005049	BDY	REMOVE/REPLACE	L Frnt Bumper Reinforcement	209 885 05 16	13.50	INC
22	000759	BDY	REMOVE/INSTALL	R Frnt Fender Shield	Existing		0.2 r

ESTIMATE RECALL NUMBER: 07/01/2011 08:57:04 33629

Mitchell Data Version: OEM: MAY_11_V UltraMate is a Trademark of Mitchell International
 Copyright (C) 1994 - 2011 Mitchell International

UltraMate Version: 7.0.331

All Rights Reserved

23	000760	BDY	REMOVE/INSTALL	L Frt Fender Shield	Existing	0.2	r
24	000780	BDY	REMOVE/INSTALL	Front Body Lower Crossmember	Existing	0.4	#r
25				Possible replacement part lists @ \$294.00. Attempt to modify if necessary.			
26							
27	000784	BDY	REMOVE/INSTALL	R Upr Front Body Bracket	Existing	0.2	#r
28	000785	BDY	REMOVE/INSTALL	L Upr Front Body Bracket	Existing	0.2	#r
29	000782	BDY	REMOVE/INSTALL	R Lwr Front Body Bracket	Existing	0.2	#r
30	000783	BDY	REMOVE/INSTALL	L Lwr Front Body Bracket	Existing	0.2	#r
31	005492	BDY	REMOVE/INSTALL	Frnt Engine Under Cover	Existing		INC #r
32	005493	BDY	REMOVE/INSTALL	Engine Guard	Existing	0.2	#r
33	936014		ADD'L COST	FLEX ADDITIVE		3.00	*
34	AUTO	REF	ADD'L OPR	Clear Coat			1.3*
35	933003	REF	ADD'L OPR	TINT COLOR			1.0*
36	AUTO	REF	ADD'L OPR	FINISH SAND AND BUFF			0.8
37	AUTO		ADD'L COST	Paint/Materials		220.50	*
38	AUTO		ADD'L COST	Hazardous Waste Disposal		5.00	*

* - Judgment Item
 # - Labor Note Applies
 C - Included in Clear Coat Calc
 r - CEG R&R Time Used For This Labor Operation

Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	6.6	56.00	0.00	0.00	369.60	Taxable Parts	673.50
Refinish	7.1	56.00	0.00	0.00	397.60	Sales Tax @ 8.750%	58.93
Non-Taxable Labor					767.20	Total Replacement Parts Amount	732.43
Labor Summary	13.7				767.20		
III. Additional Costs						IV. Adjustments	Amount
Taxable Costs					223.50	Insurance Deductible	0.00
Sales Tax @ 8.750%					19.56	Customer Responsibility	0.00
Non-Taxable Costs					5.00		
Total Additional Costs					248.06		
Paint Material Method: Rates Init Rate = 35.00 , Init Max Hours = 99.9, Addl Rate = 0.00							
I. Total Labor:						767.20	
II. Total Replacement Parts:						732.43	
III. Total Additional Costs:						248.06	
Gross Total:						1,747.69	
IV. Total Adjustments:						0.00	
Net Total:						1,747.69	

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

**** Special Parts Notice:**

All crash parts on this estimate are new-OEM (Original EquipmentManufacturer) unless otherwise specified. Parts described as Re-chromed, Recored, or Remanufactured are either Reconditioned or Rebuilt. Parts that are described as Qual Repl Part, and QRP CAPA, are Non-OEM crash parts.