

- Parts list -

Mode	BM mode	BM overview	CLS 500
VIN/mod. des.	WDD2183731A096870	Catalog	D33
VIN	WDDLJ7DB6EA096870	Group	50 RADIATOR
Assortment class	PC	Sub-group	165 EXPANSION TANK, MOUNTING AND HOSES
Market			

Copyright 2020-06-14 Daimler AG




























































Image ID: drawing_B50165000425

Item	Part number	Designation/additional information	Qty
10	A 204 500 06 49	EXPANSION RESERVOIR Replaced by: A 204 500 09 49 Code: M278+-228/M157;	1
10	A 204 500 09 49 ⚙️	EXPANSION RESERVOIR Replaces: A2045000649 Code: M278+-228/M157; 🔧 Fault location 50101	1
20	A 007 993 40 01 ⚙️	* CATCH SPRING DE-AERATION LINE TO EXPANSION TANK; 8.8 MM Code: M278/M157; 🔧 Fault location 5001W	1
40	A 210 501 06 15	CAP ON COMPENSATION RESERVOIR 🔧 Fault location 50101	1

Item	Part number	Designation/additional information	Qty
60	A 212 501 25 82 	COOLANT HOSE FROM LEFT COOLER TO ENGINE  Code: M278+(804/805/806/807/808/809)/M278+228+(803/804/805/806/807/808/809);  Fault location 50201	1
70	A 003 997 18 89 	* SEALING RING COOLANT HOSE, LEFT, TO RADIATOR; 39.3 MM Replaced by: A 026 997 67 45  Code: M278;  Fault location 5001W	1
70	A 026 997 67 45 	* O-RING COOLANT HOSE, LEFT, TO RADIATOR Replaces: A0039971889  Code: M278;  Fault location 5001W	1
80	A 003 997 18 89 	* SEALING RING COOLANT HOSE, LEFT, TO ENGINE; 39.3 MM Replaced by: A 026 997 67 45  Code: M278;  Fault location 5001W	1
80	A 026 997 67 45 	* O-RING COOLANT HOSE, LEFT, TO ENGINE Replaces: A0039971889  Code: M278;  Fault location 5001W	1
150	A 212 501 26 82 	COOLANT HOSE RIGHT AT RADIATOR  Code: (M278/M278+228)+-460;  Plant information  Fault location 50202	1
160	A 003 997 18 89 	* SEALING RING COOLANT HOSE, RIGHT, TO RADIATOR; 39.3 MM Replaced by: A 026 997 67 45  Code: M278+-460;  Fault location 5001W	1
160	A 026 997 67 45 	* O-RING COOLANT HOSE, RIGHT, TO RADIATOR Replaces: A0039971889  Code: M278+-460;  Fault location 5001W	1
170	A 003 997 18 89 	* SEALING RING COOLANT HOSE, RIGHT, TOWATER PUMP; 39.3 MM Replaced by: A 026 997 67 45  Code: M278+-460;  Fault location 5001W	1
170	A 026 997 67 45 	* O-RING COOLANT HOSE, RIGHT, TOWATER PUMP Replaces: A0039971889  Code: M278+-460;  Fault location 5001W	1
200	A 212 501 25 84 	COOLANT HOSE COOLER TO PUMP AND EXPANSION RESERVOIR  Code: M278+(152+803/804/805/806/807/808/809);  Fault location 50211	1

Item	Part number	Designation/additional information	Qty
210	A 003 997 16 89 	* SEALING RING FILLING HOSE TO RADIATOR; 21,35MM  Code: M278/M276+M002;  Fault location 5001W	1
230	A 212 501 39 84	COOLANT HOSE FROM PUMP TO SEPARATION POINT  Code: M278+(152/804/805/806/807/808/809);	1
238	A 002 995 26 77	LINE BRACKET FASTENING COOLANT HOSE  Code: M278+(152/804/805/806/807/808/809);	1
240	A 212 501 58 84	COOLANT HOSE CONNECTING POINT TO CONTAINER  Code: M278+(152/804/805/806/807/808/809);	1
248	N 000000 001114	HEXALOBULAR BOLT FASTENING COOLANT HOSE; M6X15  Code: M278+(152/804/805/806/807/808/809);	2
250	A 212 501 06 25 	BLEED LINE FROM RIGHT COOLER TO EXPANSION RESERVOIR AND ENGINE  Code: M278;  Fault location 50216	1
260	A 016 997 24 45 	* SEALING RING DE-AERATION LINE TO EXPANSION TANK; 6,07MM X 1,78 MM  Code: M278/M157;	1
270	A 016 997 24 45 	* SEALING RING DE-AERATION LINE TO RADIATOR; 6,07MM X 1,78 MM  Code: M278/M157;	1
280	A 016 997 24 45 	* SEALING RING BREATHER LINE TO ENGINE; 6,07MM X 1,78 MM  Code: M278/M157;	1
450	A 278 200 34 51	COOLANT LINE RIGHT  Code: M278+M46;  Plant information Optionally: A2782003651	1
450	A 278 200 36 51	COOLANT LINE RIGHT  Code: M278+M46;  Plant information Optionally: A2782003451	1
460	N 910143 006000	HEXALOBULAR BOLT FASTENING COOLANT HOSE; M6X12  Code: M278+M46;	1
900	A 022 545 27 26	CLUTCH HOUSING COOLANT LEVEL S41; 4-PIN MLK1.2  Fault location 59127	1