



P77.20-2478-06

	Cleaning		
 Danger!	Risk of injury caused by fingers being jammed or pinched when removing, installing or aligning hoods, doors, trunk lid/rear-end door or sliding roof.	When moving components, ensure that no body parts or limbs are within the operating range of moving parts.	AS00.00-Z-0011-01A
1	Fully open tilting/sliding roof		
2	Clean slide rails and sliding blocks (arrows) with rag		
3	Coat sliding rails and sliding blocks (arrows) thinly with grease	Klueber Polylub grease	*BR00.45-Z-1046-06A
4	Check tilting/sliding roof for proper function		
5	Close tilting/sliding roof		

Repair materials

Number	Designation	Order number
BR00.45-Z-1046-06A	Klueber Polylub GLY 801 grease	A 001 989 84 51