

Vehicle History Report

V.I.D.	YEAR	MAKE/MODEL	V.I.N.	CUSTOMER NAME
[REDACTED]	2010	MERCEDES-BENZ ML350..	45 [REDACTED]	[REDACTED]
DATE	RO #	TECH	MILES	DESCRIPTION
04/13/2010	74895	[REDACTED]	5	PDI COMPLETE
08/05/2010	76840	[REDACTED]	45	MAVS PROVIDED
02/02/2011	79669	[REDACTED]	10211	
02/02/2011	79669	[REDACTED]	10211	PERFORMED SCR CAMPAIGN
02/02/2011	79669	[REDACTED]	10211	PERFORMED A-FLEX SERVICE
07/22/2011	82307	[REDACTED]	19603	TEST DROVE AUTO, UNABLE TO DUPLICATE ANY FAULT, PERFORM QUI
07/22/2011	82307	[REDACTED]	19603	RECOMMEND MAJOR SERVICE, PERFORM MAJO SERVICE, REPLACE FUEL F
11/29/2011	84306	[REDACTED]	27070	REPLACED RF HEAD LAMP 82-1201-.2
01/13/2012	84926	[REDACTED]	29129	BULB WAS BURED OUT, REPLACED BULB 82-1201-.2
01/24/2012	85018	[REDACTED]	29409	RIGHT WIPER ARM SEDERATED AT PILOT, REPLACED RIGHT WIPER AR
02/03/2012	85177	[REDACTED]	30070	BRAKE FLUID, SERVICE B, PERFORMED SERVICE B, DECLINED ADDBL
02/03/2012	85177	[REDACTED]	30070	WASH AND VAC COMPLETE
02/28/2012	85509	[REDACTED]	30367	FOUND BATTERY DEAD- ATTEMP TO JUMP UNDERHOOD, ATTEMP TO JUMP
03/19/2012	85756	[REDACTED]	84926	see rc 84926
09/04/2012	88474	[REDACTED]	40264	UPDATE SCR SOFTWARE PER DTB
09/04/2012	88474	[REDACTED]	40264	WASH ONLY COMPLETED
09/04/2012	88474	[REDACTED]	40264	TEST DROVE AUTO, UNALBE TO DUPLICATE, PERFORM QUIC TEST, NO
09/04/2012	88474	[REDACTED]	40264	PERFORM MAJOR SERVICE
11/30/2012	89854	[REDACTED]	46225	VARIIFIED COMPLAINT, CHECKED FOR BULLETINS ON NETSTAR, CHECK
02/25/2013	91020	[REDACTED]	49226	JUMP STARTED VEHICLE
04/10/2013	91668	[REDACTED]	49980	JUMP START ATTEMPT- NOT SUCCESSFUL. REPLACE BATTERY
04/10/2013	91669	[REDACTED]	49980	TEST BATTERY WITH MIDTRONICS. STATES REPLACE. REPLACE BATTE
04/18/2013	91773	[REDACTED]	50875	REPLACED FUEL FTILTER. REPLACED ENGINE AFR FILTER.
04/18/2013	91773	[REDACTED]	50875	WASH AND VAC COMPLETE.
04/18/2013	91773	[REDACTED]	50875	MINOR SERVICE. FILL DEF, ENGINE AIR FILTERS. FUEL FILTER. D
04/18/2013	91773	[REDACTED]	50875	TEST BATTERY- STATES CHARGE. CHARGE BATTERY. CHECK FOR DRAW
09/19/2013	94316	[REDACTED]	59081	PERFORMED SERVICE, FLUSHED BRAKES.
09/19/2013	94316	[REDACTED]	59081	SMALL ROCK STUCK IN BACKING PLATE. VEHICLE DOES NEED REAR P
09/19/2013	94316	[REDACTED]	59081	CHECK ENGINE LIGHT AND GLOW PLUG LIGHT ARE ON. FAULTY GLOW
09/19/2013	94316	[REDACTED]	59081	REPLACED REAR PADS AND ROTORS.
09/27/2013	94452	[REDACTED]	59250	WASH AND VAC COMPLETED
09/27/2013	94452	[REDACTED]	59250	REPLACED GLO PLUGS AND GLOW PLUG MODULE
11/15/2013	95265	[REDACTED]	62545	PERFORMED MB ALIGNMENT.
04/22/2014	97451	[REDACTED]	67418	OIL LEAKING AT REAR OF ENGINE FROM DRAIN PIPES IN VALLEY. E
11/10/2014	100910	[REDACTED]	76094	PERFORM QUICK TEST. FAULTS FOR ADDBLUE TANK HEATING ELEMENT.
11/12/2014	100979	[REDACTED]	76120	PERFORM QUICK TEST. FAULT 20E823 STORED, ADDBLUE SYSTEM PRE
12/03/2014	101346	[REDACTED]	77612	NO PRESSURE FROM NEW ADDBLUE PUMP. VERIFY POWER AT CONNECTOR