

Brake juddering at the rear axle

Topic number	LI42.10-P-062556
Version	1
Design group	42.10 Service brake
Date	11-06-2015
Validity	Model series 207 (code 494 USA) with brake dimensions 300x22 mm
Reason for change	

Complaint:

Juddering/shuddering of the brakes at the rear axle can be felt when braking.

Cause:

Thickness of brake disk.

Remedy:

Note: Applies only in the event of complaint.

Replacement of brake linings and brake disks.

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 007 420 85 20			Brake lining set	1		X
A 000 423 12 12			Brake disk	2		X

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
40-1590			42201 H4	
42-2706			42201 H4	
42-2731			42201 H4	