

- MODEL 164**  
with CODE 498 (Japanese version)  
without CODE 849 (Spare wheel holder/spare wheel)
- MODEL 207, 212**  
up to model year 2014  
with CODE 498 (Japanese version)
- MODEL 216.3 up to 5/31/07, 221.0/1 up to 5/31/07**  
without CODE 498 (Japanese version)
- MODEL 221.0/1, 251**  
with CODE 498 (Japanese version)

#### Calibration of the backup camera

The backup camera must be calibrated in the following cases:

- After replacing the reversing camera control unit.
- After removing the reversing camera.
- After adjusting or removing the trunk lid.
- After removal of the front passenger mirror on vehicles with CODE 498 (Japan version).
- After changes to the suspension which influence the suspension level.
- After work on the steering system which influences the learned steering angle values e.g. replacing the steering angle sensor.
- When using tires with another diameter.