

















Parts Information















Parts Information

- Parts list -





Vehicle	WDDKJ5KB2CF163760 (D48)	E 350 BLUE EFFICIENCY	
Color	590 - FIRE OPAL RED - UNILAC	Equipment	201 - BLAC
FIN: WDD2073591F163760		Assortment class	PC
Group	82 ELECTRICAL SYSTEM	Sub-group	220 F

Item	Part number	Designation/additional information
10	A 207 906 03 58	REAR LAMP SIDE PANEL,LEFT  Code: (800/801/802/803)+(494/460);  Fault location 82C01
10	A 207 906 04 58 	REAR LAMP SIDE PANEL,RIGHT  Code: (800/801/802/803)+(494/460);  Fault location 82R01
30	A 207 826 01 91 	* SEALING RING SIDE PANEL,LEFT  Code: 800/801/802/803;  Fault location 82A25
30	A 207 826 02 91 	* SEALING RING RIGHT  Code: 800/801/802/803;  Fault location 82N25
100	A 207 820 03 64	TAIL LAMP TRUNK LID, LEFT  Code: (800/801/802/803);  Fault location 82C20
100	A 207 820 04 64 	TAIL LAMP TRUNK LID, RIGHT  Code: (800/801/802/803);  Fault location 82R20

Parts Information

Item	Part number	Designation/additional information
110	A 207 826 03 91 	* SEALING RING LEFT  Code: 800/801/802/803;  Fault location 82B25
110	A 207 826 04 91 	* SEALING RING RIGHT  Code: 800/801/802/803;  Fault location 82P25
130	N 000000 004145 	* BULB LEFT TAIL LAMP; 12V-16W  Fault location 82282
130	N 000000 004145 	* BULB RIGHT TAIL LAMP; 12V-16W  Fault location 82284
160	N 910112 005000	HEXAGON NUT TAILLAMP, TRUNK LID, LEFT; M5
160	N 910112 005000	HEXAGON NUT TAILLAMP, TRUNK LID, RIGHT; M5
190	A 207 821 13 36	COVER TAILLAMP, TRUNK LID, LEFT  Code: 800/801/802/803;
190	A 207 821 14 36	COVER TAILLAMP, TRUNK LID, RIGHT  Code: 800/801/802/803;
200	A 207 820 01 56 	ADDITIONAL BRAKE LAMP  Fault location 82208
210	A 207 820 00 66 	* LENS AUXILIARY STOP LAMP TO TAILGATE  Fault location 82208
250	A 221 820 08 56	LICENSE PLATE LAMP LICENSE PLATE LAMP  [003973] IMPORTANT: FLASH REAR SAM AFTER EXCHANGING PART  Code: 802/803/804;  Fault location 82C11
900	A 025 545 22 26	CLUTCH, MECHANICAL LEFT TAIL LAMP ON TRUNK LID E3/5; 6-PIN MQS

Parts Information

Item	Part number	Designation/additional information
900	A 025 545 22 26	CLUTCH, MECHANICAL RIGHT TAIL LAMP ON TRUNK LID E4/5; 6-PIN MQS
905	A 022 545 19 26	CLUTCH HOUSING LICENSE PLATE LAMP,LEFT E19/1; 2-PIN MLK1.2  Code: 802/803; Replaced by: A 029 545 10 26
905	A 029 545 10 26	COUPLING HOUSING LICENSE PLATE LAMP,LEFT E19/1; 2-PIN MLK1.2  Code: 802/803; Replaces: A 022 545 19 26
905	A 022 545 19 26	CLUTCH HOUSING LICENSE PLATE LAMP,RIGHT E19/2; 2-PIN MLK1.2  Code: 802/803; Replaced by: A 029 545 10 26
905	A 029 545 10 26	COUPLING HOUSING LICENSE PLATE LAMP,RIGHT E19/2; 2-PIN MLK1.2  Code: 802/803; Replaces: A 022 545 19 26
920	A 025 545 01 26	CLUTCH, MECHANICAL 3RD STOP LAMP E21; 2-PIN MQS