

2010 Mercedes-Benz E-Class V8, 5.5L

WDDKJ7CB9AF027052

Code Definition

Coolant temperature sensor 1 has a malfunction.

Disclaimer: The Possible Causes outlined above may or may not be the cause of your vehicle trouble code(s) being triggered. The Reported Fixes listed are suggestions only, and a fix is not guaranteed by performing any of the above potential solutions. The trouble code summary data may help you pinpoint the type of repair facility that should be consulted. It is strongly recommended that you consult with a knowledgeable professional repair facility for proper diagnosis and repair of trouble code issues. This information is provided without warranty and is subject to the Terms of Use posted at www.bluedriver.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.