

Right front seat belt or left front seat belt does not roll up completely

| | |
|-------------------|-------------------------------------------------------------------------------------|
| Topic number | LI91.40-P-053536 |
| Version | 1 |
| Function group | 91.40 - Seat belts, emergency tensioning retractors |
| Date | 4/20/12 |
| Validity | Model series 207, 218 in production period from 09.2011 up to and including 01.2012 |
| Reason for change | |

Complaint

Right front seat belt or left front seat belt does not roll up completely.

Cause

Belt strap scrapes on retractor housing.

| Attachments | |
|-------------------------------------------------------------------------------------|---------------------------------------------------------------|
| File | Description |
| Picture 1.jpg | Not OK alignment of reversible emergency tensioning retractor |
|  | |

Remedy

Realign the reversible emergency tensioning retractor within the installation tolerance.

- Slacken the mounting bolts on the reversible emergency tensioning retractor.
- Push the reversible emergency tensioning retractor at the upper mounting bolt towards the rear of the vehicle and tighten the mounting bolt.

XENTRY TIPS

- Correct the torque at the mounting bolts.



Not OK connection: Shown on model series 218 right front seat - Figure 1

OK connection: Shown on model series 218 right front seat - Figure 2

OK connection: Shown on model series 207 left front seat - Figure 3

Note: After aligning the reversible emergency tensioning retractor, unroll the belt completely.

Do not replace any belts!

| Attachments | |
|-------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|
| File | Description |
| Picture 2.jpg  | <p>OK alignment of reversible emergency tensioning retractor. Shown on right front seat in model series 218.</p> |
| Picture 3.jpg  | <p>OK alignment of reversible emergency tensioning retractor. Shown on left front seat in model series 207.</p> |

| WIS-References | | |
|-----------------|-------|------|
| Document number | Title | Note |
| | | |

XENTRY TIPS

| | | |
|------------------|--------------------------------------------------------------|-----------|
| AR91.40-P-0630EC | Remove/install seat belt with emergency tensioning retractor | Model 207 |
| AR91.40-P-0630CW | Remove/install seat belt with emergency tensioning retractor | Model 218 |

Symptoms

Body > Safety system > Seat belt > Seat belt > Belt strap sags

Body > Safety system > Seat belt > Seat belt > Belt strap rolls up poorly

Operation numbers/damage codes

| Op. no. | Operation text | Time | Damage code | Note |
|---------|----------------|------|-------------|------------------------------------|
| | | | 91A5252 | Left front seat belt inertia reel |
| | | | 91N5252 | Right front seat belt inertia reel |