

Outside door handle inoperative after operation

Topic number	LI72.00-P-055920
Version	1
Design group	72.00 General
Date	05-01-2013
Validity	MODEL 166 up to VIN end no.: A091155 MODEL 204.0 up to VIN end no.: A746680 MODEL 204.0/2/3 up to VIN end no.: F942003 MODEL 204.0 up to VIN end no.: R239870 MODEL 212 up to VIN end no.: A663422
Reason for change	

Complaint:

Outside door handle inoperative after operation. Outside door handle does not return to default position.

Cause:

Excessive play between outside door handle and slider in bearing bracket.

Remedy:

The bearing bracket and the outside door handle of the affected door must be replaced.

Note: Some parts may be non-stocking parts for MBUSA, and possibly C66 and not immediately available from DAG. Please be aware and check availability prior to scheduling customer repairs

Symptoms
Body / Door/Flap / Door / Door handle / Are loose

Parts							
Part number	ES1	ES2	Designation	Quantity	Note	EPC	Other make part
A 204 760 23 34			Bearing Bracket		Left door bearing bracket	X	
A 204 760 24 34			Bearing Bracket		Right door bearing bracket	X	
A 204 760 01 70			Door handle		Left door handle, without code 889	X	
A 204 760 02 70			Door Handle		Right door handle, without code 889	X	
A 204 760 13 70			Door Handle		Left door handle, with code 889	X	
A 204 760 14 70			Door Handle		Right door handle, with code 889	X	

Work units				
Op. no.	Operation text	Time	Damage code	Note
			72B01 38	
			72P01 38	
			73B01 38	
			73P01 38	

WIS-References			
Document number	Title	Note	Allocation
AR72.10-P-4011CW	Remove/install front door lock	Valid for model series 204/212	Remedy
AR72.12-P-2510CW	Remove/install rear door lock	Valid for model series 204/212	Remedy
AR72.10-P-2400GZ	Remove/install outside door handle on front door	Valid for model series 166	Remedy
AR72.12-P-2410GZ	Remove/install outside door handle on rear door	Valid for model series 166	Remedy
AR72.10-P-4011GQ	Remove/install front door lock	Valid for model series 166	Remedy
AR72.12-P-2510GQ	Remove/install rear door lock	Valid for model series 166	Remedy