

Service Campaign Bulletin



Mercedes-Benz

Campaign No. 2016090006, **January** 2016

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model 204**
Model Years 2008 and 2009
Replace Driver-Side and Front Passenger Air Bag

Based on the defect decision of TK Holdings, Inc (“Takata”), in certain driver-side airbags and passenger side airbags produced by Takata used in certain Model Year 2008–2009 Mercedes-Benz vehicles, under certain circumstances, the driver-side or passenger side airbag inflator housing may rupture during deployment due to excessive internal pressure. Replacement driver and passenger airbags (Like-for-Like) are available only for the **654** MY08-09 C-Class (W204) cars flagged in VMI currently in dealer inventory under the retail hold. An authorized Mercedes-Benz Dealer will replace the driver-side airbag and passenger-side airbag on the affected vehicles.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately **654** vehicles are involved.

Order No. P-SC-2016090006

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin