

- Parts list -

Mode	BM mode	BM overview	E 350 4MATIC
VIN/mod. des.	WDD2120881A625191	Catalog	D04
VIN	WDDHF8JB5CA625191	Major assembly	Chassis
Assortment class	PC	Major assy. mod. des.	C212088
Market		Group	20 ENGINE COOLING
		Sub-group	015 WATER PUMP






































Image ID: drawing_B20015000528

Item	Part number	Designation/additional information	Qty
------	-------------	------------------------------------	-----

Copyright 2020-05-30 Daimler AG

Item	Part number	Designation/additional information	Qty
10	A 276 200 13 01	WATER PUMP  [697] PART IS ONLY OR ALSO SUPPLIED AS RECONDITIONED PART  Plant information  Fault location 20001  Alternative parts are available	1
20	A 276 201 00 80	METAL SEAL, SINGLE LAYER WATER PUMP TO TIMING CASE COVER AND TO CRANKCASE,RESP. Replaced by: A 276 201 07 80  Plant information  Fault location 20009	1
20	A 276 201 07 80	METAL SEAL, SINGLE LAYER WATER PUMP TO TIMING CASE COVER AND TO CRANKCASE,RESP. Replaces: A2762010080  Plant information  Fault location 20009	1
25	A 276 201 06 03	WATER PUMP COVER Replaced by: A 276 201 02 03  Plant information  Fault location 20001	1
25	A 276 201 02 03	WATER PUMP COVER Replaces: A2762010603  Plant information  Fault location 20001	1
28	A 004 990 44 12	SCREW COVER TO WATER PUMP	3
30	N 000000 003967	HEXALOBULAR BOLT WATER PUMP TO TIMING CASE COVER AND TO CRANKCASE,RESP.; M8X75	4
35	N 000000 002252	HEXALOBULAR BOLT WATER PUMP AT CRANKCASE	1
40	N 000000 002770	HEXALOBULAR BOLT WATER PUMP TO TIMING CASE	6
50	A 102 991 03 41	PILOT BUSHING BOTTOM SIDE OF WATER PUMP  Plant information  Fault location 01078	2
60	A 276 200 01 15	COOLANT THERMO. W HOUSING Replaced by: A 276 200 05 15  Plant information  Fault location 20102, 2030T	1

Item	Part number	Designation/additional information	Qty
60	A 276 200 05 15 	COOLANT THERMO. W HOUSING Replaces: A2762000115  Fault location 20102, 2030T	1
70	A 000 993 12 02 	* CATCH SPRING THERMOSTAT; SCB36 46.4MM  Fault location 5001W	1
80	A 021 997 92 45 	* O-RING THERMOSTAT  Fault location 07304	1
85	A 276 201 06 80 	* ELASTOMER MOLDED SEAL  Fault location 20105	1
90	A 276 203 00 02	COOLANT PIPE Replaced by: A 276 203 01 02  Plant information  Fault location 20405	1
90	A 276 203 01 02	COOLANT PIPE Replaces: A2762030002  Fault location 20405	1
100	N 000000 001101	HEXALOBULAR BOLT THERMOSTAT TO WATER PUMP	3
110	A 276 200 01 56 	COOLANT INLET CONNECTION COOLING WATER  Fault location 20031	1
115	A 000 993 12 02 	* CATCH SPRING SCB36 46.4MM  Fault location 5001W	1
120	A 276 201 02 80 	* ELASTOMER MOLDED SEAL  Fault location 20032	1
125	N 000000 001147	HEXALOBULAR BOLT PIPE SOCKET TO WATER PUMP; M6X20	2
130	N 000000 001422	HEXALOBULAR BOLT FITTING TO TIMING CASE; M6X30  Fault location 20033	1
900	A 022 545 19 26	CLUTCH HOUSING HEATING ELEMENT R48/1; 2-PIN MLK1.2 Replaced by: A 029 545 10 26	1
900	A 029 545 10 26	COUPLING HOUSING HEATING ELEMENT R48/1; 2-PIN MLK1.2 Replaces: A0225451926	1
901	A 000 982 28 26	CRIMP CONNECTOR CONTACT 0.22-0.35 MM2 MLK1.2S	NB
901	A 000 982 30 26	CRIMP CONNECTOR CONTACT 0.75-1.0 MM2 MLK1.2S	NB

Item	Part number	Designation/additional information	Qty
901	A 001 545 50 80	SINGLE-WIRE SEAL YELLOW; 0.22-1.0 MM2 MLK1.2	NB

Copyright 2020-05-30 Daimler AG