

- Parts list -

<b>Vehicle</b>	WDDKJ6FB9GF346255 (D48)	E 400 BLUE EFFICIENCY	
<b>Color</b>	040 - undefined	<b>Equipment</b>	264 -
FIN: WDD2073651F346255		<b>Assortment class</b>	PC
<b>Group</b>	82 ELECTRICAL SYSTEM	<b>Sub-group</b>	175 FRONT ILLUMINATION


































Image ID: drawing\_B82175000296

Item	Part number	Designation/additional information	Qty
10	A 207 820 83 61 🔧	LAMP UNIT LEFT 📦 Code: (804/805/806/807)+632+(494/460); 🔧 Fault location 82B01	1
10	A 207 820 84 61 🔧	LAMP UNIT RIGHT 📦 Code: (804/805/806/807)+632+(494/460); 🔧 Fault location 82P01	1
50	N 400809 000007 🔧	* BULB MAIN BEAM LEFT; H7 12V-55W 📦 Code: 631/632; 🔧 Fault location 82123	2
80	N 000000 007501 🔧	* BULB LEFT BLINKER LIGHT; 12V - 24W 📦 Code: 631/632; 🔧 Fault location 82268	1
80	N 000000 007501 🔧	* BULB RIGHT BLINKER LIGHT; 12V - 24W 📦 Code: 631/632; 🔧 Fault location 82268	1

## Parts Information

Item	Part number	Designation/additional information	Qty
120	A 208 820 02 49 	* CAP MAIN BEAM LEFT  Code: 631/632;  Fault location 82155	2
130	A 207 826 09 91 	* GASKET FOR LIGHT HOUSING Left  Fault location 82B00	1
130	A 207 826 10 91 	* GASKET FOR LIGHT HOUSING Right  Fault location 82P00	1
140	A 023 420 75 18 	* DIAPHRAGM UNIT LEFT  Code: 631/632/641/642;	1
140	A 023 420 75 18 	* DIAPHRAGM UNIT RIGHT  Code: 631/632/641/642;	1
200	A 001 990 52 00	COMBI-HEXAGON HEAD BOLT MOUNTING HEADLAMP LEFT; M5X16	1
200	A 001 990 52 00	COMBI-HEXAGON HEAD BOLT MOUNTING HEADLAMP RIGHT; M5X16	1
200	A 000 990 90 00	COMBI-HEXAGON HEAD BOLT ATTACHMENT HEADLAMP; M5X42,5	4
220	A 207 820 05 14	RS BRACKET LEFT BRACKET  Code: 804/805/806/807;	1
220	A 207 820 06 14	RS BRACKET RIGHT BRACKET  Code: 804/805/806/807;	1
230	A 212 900 53 24 	CONTROL UNIT, COMPLETE HEADLAMP RANGE ADJUSTMENT LEFT  [672] PART MUST BE CHECKED FOR CURRENT FLASHWARE AFTER INSTALLATION  Code: (804/805/806/807)+(631/632);  Fault location 82B03,82P03 <b>Replaced by: A 218 900 72 06</b>	1
230	A 218 900 72 06 	CONTROL UNIT, COMPLETE HEADLAMP RANGE ADJUSTMENT LEFT  [672, 697] PART MUST BE CHECKED FOR CURRENT FLASHWARE AFTER INSTALLATION  Code: (804/805/806/807)+(631/632);  Fault location 82B03,82P03 <b>Replaces: A 212 900 53 24</b>	1
230	A 212 900 53 24 	CONTROL UNIT, COMPLETE HEADLAMP RANGE ADJUSTMENT RIGHT  [672] PART MUST BE CHECKED FOR CURRENT FLASHWARE AFTER INSTALLATION  Code: (804/805/806/807)+(631/632);  Fault location 82B03,82P03 <b>Replaced by: A 218 900 72 06</b>	1
230	A 218 900 72 06 	CONTROL UNIT, COMPLETE HEADLAMP RANGE ADJUSTMENT RIGHT  [672, 697] PART MUST BE CHECKED FOR CURRENT FLASHWARE AFTER INSTALLATION  Code: (804/805/806/807)+(631/632);  Fault location 82B03,82P03 <b>Replaces: A 212 900 53 24</b>	1
240	A 000 826 04 00	GASKET FOR LIGHT HOUSING HEADLAMP RANGE ADJUSTMENT CONTROL UNIT AT LEFT  Code: (631/632);	1

## Parts Information

Item	Part number	Designation/additional information	Qty
240	A 000 826 04 00	GASKET FOR LIGHT HOUSING HEADLAMP RANGE ADJUSTMENT CONTROL UNIT AT RIGHT Code: (631/632);	1
250	A 207 901 37 00	CONTROL UNIT RAIN AND LIGHT SENSOR Fault location 82128	1
270	N 000000 002856 	PAN HEAD SCREW HEADLAMP RANGE ADJUSTMENT CONTROL UNIT TO LEFT HEADLAMP Code: (631/632/640/641/642);	4
270	N 000000 002856 	PAN HEAD SCREW HEADLAMP RANGE ADJUSTMENT CONTROL UNIT TO RIGHT HEADLAMP Code: (631/632/640/641/642);	4
305	N 000000 001606 	* BULB FOGLAMP; H11 12V-55W Fault location 82137 Replaced by: N 000000 008143	1
305	N 000000 008143 	* BULB FOGLAMP; H11 12V-55W Fault location 82137 Replaces: N 000000 001606	1
450	A 207 820 03 21	TURN SIGNAL LAMP SIDE-MARKER LAMP LEFT Code: 264; Fault location 82C14	1
450	A 207 820 04 21	TURN SIGNAL LAMP SIDE-MARKER LAMP RIGHT Code: 264; Fault location 82R14	1
460	N 000000 006369	BULB SIDE MARKER LAMP; 12V-5W Fault location 82280	2
900	A 052 545 56 26	COUPLING HOUSING LEFT FRONT LIGHTING UNIT E1/6; 14-PIN SLK2.8, MLK1.2 Code: 615/621/622/494+615/631/632/640/641/642;	1
900	A 052 545 56 26	COUPLING HOUSING RIGHT FRONT LIGHTING UNIT E2/6; 14-PIN SLK2.8, MLK1.2 Code: 615/621/622/494+615/631/632/640/641/642;	1
905	A 000 540 09 66	SOCKET SIDE-MARKER LAMP LEFT E6/3	1
905	A 000 540 09 66	SOCKET SIDE-MARKER LAMP RIGHT E6/4	1
920	A 022 545 19 26	COUPLING HOUSING LEFT DAYTIME RUNNING LIGHT, LED E1/3; 2-PIN MLK1.2 Replaced by: A 029 545 10 26	1
920	A 029 545 10 26	COUPLING HOUSING LEFT DAYTIME RUNNING LIGHT, LED E1/3; 2-PIN MLK1.2 Replaces: A 022 545 19 26	1
920	A 022 545 19 26	COUPLING HOUSING RIGHT DAYTIME RUNNING LIGHT, LED E1/4; 2-PIN MLK1.2 Replaced by: A 029 545 10 26	1
920	A 029 545 10 26	COUPLING HOUSING RIGHT DAYTIME RUNNING LIGHT, LED E1/4; 2-PIN MLK1.2 Replaces: A 022 545 19 26	1