

Fading of wood trim in model series 212

Topic number	LI68.30-P-053962
Version	4
Design group	68.30 Coverings, trim
Date	11-25-2013
Validity	Affected vehicles: MODEL 212 with CODE (731) Burlled walnut veneer wood finish trim MODEL 212 with CODE (W 60) Burlled walnut veneer designo wood trim, brown
Reason for change	Damage type revised

Complaint:

Fading of the burlled walnut veneer wood finish trim parts

Cause:

UV radiation may cause fading in some cases

Remedy:

Affected vehicles:

MODEL 212 with CODE (731) Burlled walnut veneer wood finish trim

MODEL 212 with CODE (W60) Burlled walnut veneer designo wood trim, brown

In the event of complaints, parts kits of burlled walnut veneer wood finish trim are available from the GLC

Encode the affected component with damage type "26"

Symptoms
Body / Interior equipment / Door paneling / Discolored
Body / Interior equipment / Instrument panel / Surface discolored
Body / Interior equipment / Interior trim / Discolored

Parts							
Part number	ES1	ES2	Designation	Quantity	Note	EPC	Other make part
A2126801293			Parts kit: Burlled walnut veneer wood finish trim parts	1	LHD with steering wheel gearshift (code 279)		X

Work units				
Op. no.	Operation text	Time	Damage code	Note
				Encode the affected component with damage type "26"