


- Parts list -





























Mode	BM mode	BM overview	E 220 D
VIN/mod. des.	WDD2130042A048206	Catalog	C213_FW
VIN		Group	47 FUEL SYSTEM
Assortment class	PC	Sub-group	800 ADBLUE CONTAINER AND LINES
Market			



Copyright 2020-03-13 Daimler AG

Image ID: drawing_B4780000083

Item	Part number	Designation/additional information	Qty
10	A 213 470 60 01	ADDITIVE TANK Replaced by: A 213 470 93 01 Code: (U79+U85)+(807/808); Plant information Fault location 47071	1
10	A 213 470 93 01 	ADDITIVE TANK Replaces: A2134706001 Code: (U79+U85)+(807/808); Plant information Fault location 47071	1

Item	Part number	Designation/additional information	Qty
30	A 099 140 00 00 	* RS CONNECTION FITTING WITH FASTENING BOLTS  Code: U79;  Fault location 47305	1
33	A 099 470 08 00 	* RS METERING PUMP WITH FASTENING BOLTS  Code: U79;  [697] PART IS ONLY OR ALSO SUPPLIED AS RECONDITIONED PART  Fault location 47305	1
35	A 099 905 79 00 	* PRESSURE SENSOR WITH FASTENING BOLTS  Code: U79;  Fault location 47305	1
38	A 099 340 00 00 	* RS SERVICE COVER WITH FASTENING BOLTS  Code: U79;  Fault location 47305	1
100	A 213 475 00 27	BRACKET TANK TO WHEEL WELL, OUTSIDE  Code: U77/U79/6U7;  Fault location 47049	1
110	N 910112 006001	HEXAGON NUT HOOK TO SIDE PANEL; M6  Code: U77/U79/6U7;	2
120	A 003 990 96 03	COMBI-SCREW W FEATURE TANK TO VEHICLE; M8X43  Code: (U77/U79/6U7)+U85;  Fault location 47024	3
150	A 213 470 02 00	FILLER PIPE  Code: U77/U79;  Plant information  Fault location 47082	1
160	A 000 470 43 05	FILLER CAP  Code: U77/U79;  Plant information  Fault location 47048	1
200	A 003 998 63 50	STOP PLUG ON SIDE MEMBER M8  Code: (U77/U79/6U7)+U85;	2
200	A 003 998 63 50	STOP PLUG SIDE MEMBER LATERAL REAR RIGHT  Code: U77/U79/6U7;	1
630	A 004 995 38 77	LINE FASTENER ADDITIVE LINE FASTENING  Code: (U77/U79/6U7)+-228;  Fault location 47312	1