

## Splitting of Seat Covers

---

Topic number	LI91.10-P-063393
Version	1
Design group	91.10 Front seats
Date	02-22-2016
Validity	117, 156, Before VIN A27110 on 166, 172, 204, X204 212, 246
Reason for change	

---

### Complaint:

Splitting of seat covers

### Cause:

Currently being investigated.

Note: Please see pictures for examples of what above damages looks like.

Attachments	
File	Description
CIMG3876.JPG	Splitting 1
CIMG3875.JPG	Splitting 2
CIMG3870.JPG	Splitting 3
Pictures.pdf	Splitting 4

### Remedy:

Replace Seat Covers as needed.