

Model 205 Model 213 Model 253 Model 293





P42.10-3001-08

Shown on right side of vehicle on model 205, except code B07 (Ceramic brake system)

- 1 Brake linings
- Caliper support

- 3 Brake disk
- 4 Screw

| | Risk of accident when commissioning the vehicle due to a lack of braking effect when the service brake is operated for the first time after repair work. | Before starting the engine, actuate brake pedal several times until pressure is built up and maintained in the brake system. | AS42.50-Z-0002-01A |
|-------------|--|---|---------------------|
| ⚠ Caution | Risk of poisoning from swallowing brake fluid. Risk of injury from skin and eye contact with brake fluid | Only pour brake fluid into suitable and appropriately marked containers. Wear protective clothing and eye protection when handling brake fluid. | AS42.50-Z-0001-01A |
| ⚠ Warning | Risk of injury . Skin or eye injuries may result when handling hot or glowing objects. | Wear protective gloves, protective clothing and safety glasses, if necessary. | AS00.00-Z-0002-01A |
| | Notes on handling, transport and storage of composite brake disks | | AH42.10-P-9406-12LF |
| | Notes on handling, transport and storage of ceramic brake disks | | AH42.10-P-9406-13A |
| | Notes on self-locking nuts and bolts | | AH00.00-N-0001-01A |
| | Brake fluid notes | | AH42.50-P-0001-01A |
| | Notes on repairs to brake system | | AH42.00-P-0003-01A |
| | Notes on safety-relevant components | | AH00.00-Z-0019-01A |
| X | Remove | | |
| 1 | Detach brake caliper and secure free of tension to vehicle with lines still connected. | Do not subject the brake hose and electrical line to tension and do not kink them. The brake hose and the electrical line can otherwise be damaged. | AR42.10-P-0080LW |
| 2 | Remove brakepads (1) from brake caliper support (2). | | |
| 3 | Pull right rear brakepad wear sensor out of backing plate of brakepad (1). | When replacing the brake linings (1) or right rear brake wear sensor. | |
| 4 | Check | | |
| 4 | Check brakepads (1) for wear and condition. | | |
| ⊯ AP | | Model 293 | AP42.10-P-4252EQ |
| F≆AP | | Model 205 | AP42.10-P-4252CAA |
| F≆AP | | Model 253 | AP42.10-P-4252D |

| F≆AP | | Model 213 | AP42.10-P-4252E |
|----------|---|---|---------------------|
| | | If a problem arises | |
| | | ↓ | |
| | | Replace brake linings (1) in sets. | |
| ₩ | Clean | | |
| 5 | Clean contact surfaces of brakepads (1) on brake caliper support (2) (arrows) and on brake caliper. | Do not use sharp-edged or pointed objects. Otherwise, the brake caliper, the dust boot on the brake piston or the brake caliper support (2) may be damaged. | |
| | | Assembly cleaner | *BR00.45-Z-1028-04A |
| X | Install | | |
| 6 | Insert rear right brakepad wear sensor on backing plate of brakepad (1). | When replacing the brake linings (1) or right rear brake wear sensor. | |
| 7 | Apply brake paste to brake caliper and to brake caliper support (2). | | AR42.10-P-0163-01LW |
| | | i The brake paste to be used depends on the manufacturer of the brake caliper. | |
| | | Lubricant paste | *BR00.45-Z-1130-06A |
| | | Brake paste, Varybond | *BR00.45-Z-1072-06A |
| 8 | Insert brakepads (1). | i Only brakepads (1) approved by Mercedes-Benz may be installed, and only as complete sets. | |
| 9 | Install brake caliper. | | AR42.10-P-0080LW |

Repair materials

| Number | Designation | Order number |
|--------------------|-----------------------|--------------------|
| BR00.45-Z-1028-04A | Assembly cleaner | A 000 986 56 01 |
| BR00.45-Z-1072-06A | Brake paste, Varybond | A 001 989 94 51 |
| BR00.45-Z-1130-06A | Lubricant paste | A 000 989 98 00 09 |