

Semiconductor Announcements

Note: Due to the current worldwide shortage of supply in certain semiconductor components, there are delays in vehicle delivery.

Week of 8/8/2021

- **MY22 GLC43W4/GLC43C4:**
 - From November production until the constraint ends, on Burmester Surround Sound System (810), Midline Sound System (853) will be available as the upgraded sound system option. For more details on 853, please refer to the AMG GLC DOGs.

Week of 7/19/2021

- **MY22 GT43C4/GT53C4:**
 - NFC Wireless Charging removed from standard; credit code (D6J) of \$200 assigned
- **MY22 C300W/C300W4:**
 - Burmester 3D Surround Sound System (810) removed from options
 - HANDS-FREE ACCESS (871) removed from standard; credit code (D9B) of \$100 assigned
- **MY22 C300A/C300A4/C300C/C300C4:**
 - HANDS-FREE ACCESS (871) removed from standard; credit code (D9B) of \$100 assigned
 - Inductive Wireless Charging & NFC Pairing (897) removed from options
- **MY22 GLC300/GLC300W4/GLC300C4:**
 - Augmented Video for Navigation (U19) removed from options
 - Dashcam (21U) removed from options
 - Burmester Surround Sound System (810) removed from options
 - 12.3" Digital Instrument Cluster (464) removed from options
 - HANDS-FREE ACCESS (P17/871) on Coupe removed from standard; credit code (D9B) of \$100 assigned. HANDS-FREE ACCESS (P17/871) on SUV removed from options
 - Inductive Wireless Charging and NFC Pairing (897) removed from options
- **MY22 GLE350W/GLE350W4/GLE450W4:**

- Augmented Video for Navigation (U19) removed from options
- Dashcam (21U) removed from options
- Wireless Charging with NFC Pairing removed from standard; credit code (D6J) of \$200 assigned
- **MY21 GLE350W/GLE350W4/GLE450W4/GLE580W4:**
 - Augmented Video for Navigation (U19) removed from options
 - Dashcam (21U) removed from options
- **MY22 GLE53C4/GLE53W4:**
 - Augmented Video for Navigation (U19) removed from options
 - Dashcam (21U) removed from options
 - Wireless Charging with NFC Pairing (897) removed from standard; credit (D6J) code of \$200 applied
 - 63S model only - AMG Track Pace (256) removed from standard equipment
 - 53 model only - AMG Track Pace (256) removed from AMG Dynamic Plus Package; replaced with AMG Dynamic Plus Package Lite (DT1)
- **MY22 GLS450W4:**
 - Augmented Video for Navigation (U19) removed from options
 - Dashcam (21U) removed from options
 - Wireless Charging with NFC Pairing removed from standard; credit code (D6J) of \$200 assigned
- **MY21 GLS450W4/GLS580W4:**
 - Augmented Video for Navigation (U19) removed from options
 - Dashcam (21U) removed from options
- **MY22 GLC43C4/GLC43W4:**
 - 12.3" Digital Instrument Cluster (464) removed from standard; credit code (D8J) of \$750 assigned
 - HANDS-FREE ACCESS (871) removed from standard; credit code (D9B) of \$100 assigned
 - Burmester Surround Sound (810) removed from options
 - Inductive Wireless Charging (897) removed from options
- **MY21 GLC63C4/GLC63C4S/GLC63W4:**
 - Augmented Video (U19) removed from standard; credit code (D6K) of \$350 assigned
 - Burmester (810) removed from standard; credit code (D8V) of \$850 assigned
 - 12.3" Digital Instrument Cluster (464) removed from standard; credit code (D8J) of \$750 assigned
- **MY21 GLC43C4/GLC43W4/GLC63C4/GLC63C4S/GLC63W4:**
 - HANDS-FREE ACCESS (871) removed from options
 - AMG Track Pace (256) removed from options

- AMG Track Pace (256) removed from options
- Inductive Wireless Charging (897) removed from options
- **MY22 C43C4:**
 - HANDS-FREE ACCESS (871) removed from standard; credit code (D9B) of \$100 assigned
 - Inductive Wireless Charging with NFC Pairing (897) removed from options
- **MY21 C43C4/C63C/C63CS:**
 - HANDS-FREE ACCESS (871) removed from standard; credit code (D9B) of \$100 assigned
 - Inductive Wireless Charging with NFC Pairing (897) removed from options
- **MY22 C43A4:**
 - Inductive Wireless Charging with NFC Pairing (897) removed from options
- **MY21 C43A4/C63A/C63AS:**
 - Inductive Wireless Charging with NFC Pairing (897) removed from options

Week of 7/12/2021

- **MY22 E53W4:**
 - Augmented Video for Navigation (U19) removed from options
 - Dashcam(21U) removed from options
 - HANDS-FREE ACCESS (871) removed from standard equipment; credit code (D9B) of \$100 assigned
 - AMG Track Pace (256) removed from options
- **MY22 E53C4:**
 - Augmented Video for Navigation (U19) removed from options
 - Dashcam (21U) removed from options
 - HANDS-FREE ACCESS (871) removed from standard; credit code (D9B) of \$100 assigned
 - AMG Track Pace (256) removed from options
- **MY22 E53A4:**
 - Augmented Video for Navigation (U19) removed from options
 - Dashcam (21U) removed from options
 - HANDS-FREE ACCESS (871) removed from standard; credit code (D9B) of \$100 assigned
 - AMG Track Pace (256) removed from options
- **MY22 GT43C4:**

- Augmented Video for Navigation (U19) removed from options
 - Dashcam (21U) removed from options
 - HANDS-FREE ACCESS (871) removed from standard; credit code of \$100 assigned
 - AMG Track Pace (256) removed from standard; credit code (D8R) of \$250 assigned
- **MY22 GT53C4:**
 - Augmented Video for Navigation (U19) removed from options
 - Dashcam (21U) removed from options
 - HANDS-FREE ACCESS (871) removed from standard; credit code of \$100 assigned
 - AMG Track Pace (256) removed from standard; credit code (D8R) of \$250 applied

Week of 7/5/2021

- **MY22 GLC43C4/GLC43W4:**
 - Augmented Video for Navigation (U19) removed from DA5 Multimedia Package (\$1295); replaced with DF8 Multimedia Package Lite (\$945)
- **MY21 GLC43C4/GLC43W4:**
 - Augmented Video for Navigation (U19) removed from DA5 Multimedia Package (\$1295); replaced with DF8 Multimedia Package Lite (\$945)

Week of 6/21/2021

- **MY22 E53C4/E53A4/E53W4/E350W/E350W4/E450W4/E450S4:**
 - Standard Widescreen Digital Instrument Cluster (868) constrained; replaced with 10.25" screen in certain instances; credit code (D8J) of \$150 applied where applicable
- **MY22 S500V4/S580V4:**
 - MBUX High-End Rear Entertainment System (DB7) no longer available for ordering with Executive Line (DX2)

Week of 6/14/2021

- **MY22 S500V4/S580V4:**
 - Active Ambient Lighting (878) is no longer standard; replaced with 64-Color Ambient Lighting (891)
- **MY22 EQS450V/EQS580V4:**
 - Active Ambient Lighting (878) no longer standard; replaced with 64-Color Ambient Lighting (894)

Week of 6/7/2021

- **MY21 A35W4 Sedan:**
 - PRE-SAFE (299) removed from Driver Assistance Package (DA2); replaced with Driver Assistance Package Lite (DF5)
 - Augmented Video for Navigation (U19) removed from Multimedia Package (DA5); replaced with Multimedia Package Lite (DF8)
- **MY21 A220W/A220W4 Sedan:**
 - PRE-SAFE (299) removed from Driver Assistance Package (DA2); replaced with Driver Assistance Package Lite (DF5)
 - Augmented Video for Navigation (U19) removed from Multimedia Package (DA5); replaced with Multimedia Package Lite (DF8)
- **MY22 A220W/A220W4 Sedan:**
 - PRE-SAFE (299) removed from Driver Assistance Package (DA2); replaced with Driver Assistance Package Lite (DF5)
 - Augmented Video for Navigation (U19) removed from Multimedia Package (DA5); replaced with Multimedia Package Lite (DF8)
 - KEYLESS-GO Comfort Package (P17) removed from Premium Package (DP1) until further notice; replaced with Premium Package Lite (DF9)
- **MY21 CLA35C4/CLA45C4 Coupe:**
 - PRE-SAFE (299) removed from Driver Assistance Package (DA2); replaced with Driver Assistance Package Lite (DF5)
 - Augmented Video for Navigation (U19) removed from Multimedia Package (DA5); replaced with Multimedia Package Lite (DF8)
- **MY21 CLA250C/CLA250C4 Coupe:**
 - PRE-SAFE (299) removed from Driver Assistance Package (DA2); replaced with Driver Assistance Package Lite (DF5)
 - Augmented Video for Navigation (U19) removed from Multimedia Package (DA5); replaced with Multimedia Package Lite (DF8)

- **MY22 CLA35C4/CLA45C4 Coupe:**

- PRE-SAFE (299) removed from Driver Assistance Package (DA2); replaced with Driver Assistance Package Lite (DF5)
- Augmented Video for Navigation (U19) removed from Multimedia Package (DA5); replaced with Multimedia Package Lite (DF8)
- 35 model only - Premium Package (DP1) removed from offering until further notice; Mirror Package becomes standalone option.
- AMG Track Pace (256) no longer available
- 45 model only - AMG Track Pace (256) removed from AMG Dynamic Plus Package; replaced with AMG Dynamic Plus Package Lite (DT1)

- **MY22 CLA250C/CLA250C4 Coupe:**

- PRE-SAFE (299) removed from Driver Assistance Package (DA2); replaced with Driver Assistance Package Lite (DF5)
- Augmented Video for Navigation (U19) removed from Multimedia Package (DA5); replaced with Multimedia Package Lite (DF8)
- KEYLESS-GO Comfort Package (P17) removed from Premium Package (DP1) until further notice; replaced with Premium Package Lite (DF9)

- **MY21 GLA35W4/GLA45W4 SUV:**

- Electric Tailgate (890) no longer available; credit code (D9A) of \$300 applied
- PRE-SAFE (299) removed from Driver Assistance Package (DA2); replaced with Driver Assistance Package Lite (DF5)
- Augmented Video for Navigation (U19) removed from Multimedia Package (DA5); replaced with Multimedia Package Lite (DF8)

- **MY21 GLA250W/GLA250W4 SUV:**

- Electric Tailgate (890) no longer available; credit code (D9A) of \$300 applied
- PRE-SAFE (299) removed from Driver Assistance Package (DA2); replaced with Driver Assistance Package Lite (DF5)
- Augmented Video for Navigation (U19) removed from Multimedia Package (DA5); replaced with Multimedia Package Lite (DF8)

- **MY22 GLA35W4/GLA45W4 SUV:**

- Electric Tailgate (890) no longer available; credit code (D9A) of \$300 applied
- PRE-SAFE (299) removed from Driver Assistance Package (DA2); replaced with Driver Assistance Package Lite (DF5)
- Augmented Video for Navigation (U19) removed from Multimedia Package (DA5); replaced with Multimedia Package Lite (DF8)
- 35 model only - Premium Package (DP1) removed from offering until further notice; Mirror Package becomes standalone option

standalone option.

- AMG Track Pace (256) no longer available
- 45 model only - AMG Track Pace (256) removed from AMG Dynamic Plus Package; replaced with AMG Dynamic Plus Package Lite (DT1)
- **MY22 GLA250W/GLA250W4 SUV:**
 - Electric Tailgate (890) no longer available; credit code (D9A) of \$300 applied
 - PRE-SAFE (299) removed from Driver Assistance Package (DA2); replaced with Driver Assistance Package Lite (DF5)
 - Augmented Video for Navigation (U19) removed from Multimedia Package (DA5); replaced with Multimedia Package Lite (DF8)
 - KEYLESS-GO Comfort Package (P17) removed from Premium Package (DP1) until further notice; replaced with Premium Package Lite (DF9)
- **MY21 GLB35W4 SUV:**
 - PRE-SAFE (299) removed from Driver Assistance Package (DA2); replaced with Driver Assistance Package Lite (DF5)
 - Augmented Video for Navigation (U19) removed from Multimedia Package (DA5); replaced with Multimedia Package Lite (DF8)
- **MY21 GLB250W/GLB250W4 SUV:**
 - PRE-SAFE (299) removed from Driver Assistance Package (DA2); replaced with Driver Assistance Package Lite (DF5)
 - Augmented Video for Navigation (U19) removed from Multimedia Package (DA5); replaced with Multimedia Package Lite (DF8)
- **MY22 GLB35W4 SUV:**
 - Electric Tailgate (890) no longer available; credit code (D9A) of \$300 applied
 - PRE-SAFE (299) removed from Driver Assistance Package (DA2); replaced with Driver Assistance Package Lite (DF5)
 - Augmented Video for Navigation (U19) removed from Multimedia Package (DA5); replaced with Multimedia Package Lite (DF8)
 - Premium Package (DP1) removed from offering until further notice; Mirror Package becomes standalone option.
 - AMG Track Pace (256) no longer available
- **MY22 GLB250W/GLB250W4 SUV:**
 - Electric Tailgate (890) no longer available; credit code (D9A) of \$300 applied
 - PRE-SAFE (299) removed from Driver Assistance Package (DA2); replaced with Driver Assistance Package Lite (DF5)
 - Augmented Video for Navigation (U19) removed from Multimedia Package (DA5); replaced with Multimedia Package Lite (DF8)

- KEYLESS-GO Comfort Package (P17) removed from Premium Package (DP1) until further notice; replaced with Premium Package Lite (DF9)
-