

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
	07	MERCEDES GL320CDI	4JGBF22E47A228224		3621/3627	T448	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
23FEB07	IS12FEB07		17:00 15MAY07		92.00	CASH	15MAY07
R.O. OPENED	READY	OPTIONS: STK:9811 DLR:59215 1)164822-1A-228224					
12:53 15MAY07	15:29 15MAY07	2)TR 204					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A	TOW IN BY AAA						
CAUSE: .							
	002	SUBLET REPAIR					
	3	WM		0.00			(N/C)

3621

B CUST STATES VEH HAS NO POWER! FOUND HOSE CLAMP (PART ON SEAT)

CAUSE: .

541011	SHORT TEST, PERFORM						
	3	WM		0.30			(N/C)
	1	164-528-11-82-28	HOSE				(N/C)
541012	TEST PROGRAM - AFTER SHORT TEST, PERFORM						
	3	WM		0.50			(N/C)
098670	AIR COOLER INLET PIPE, REPL.						
	3	WM		0.70			(N/C)

3627 CHARGE AIR HOSE BLOWN OFF///// REPAIRED PER DTB 09.41/28.
 PERFORMED SHORT TEST. REPLACED CHARGE AIR HOSE. DIAGNOSTIC TIME PUNCH
 FOR BELOW ITEMS. CONTACTED EDAC, CASE #621302. FAXED COPY OF SHORT TEST
 TO EDAC AGENT.

C** NC INSPECTION

01	NC INSPECTION						
	3	IN		0.20			(N/C)

DISCLAIMER OF WARRANTIES		DESCRIPTION	TOTALS
The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items. All items with an "88" suffix are remanufactured. AUTHORIZATION FOR REPAIRS "I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspections. An express mechanic's lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. Not responsible for damage from freezing due to lack of antifreeze."		LABOR AMOUNT	
		PARTS AMOUNT	
		GAS, OIL, LUBE	
		SUBLET AMOUNT	
		MISC. CHARGES	
		TOTAL CHARGES	
		LESS INSURANCE	
		SALES TAX	
		PLEASE PAY THIS AMOUNT	
		CUSTOMER SIGNATURE _____	

CUSTOMER COPY