

Thumping Noise from Front Axle

Model

164.122/175/177/186/822/871,
Model 251.122/165/175/177

If there are thumping noises coming from the front axle when driving over bumps, retighten the bolted connections to 200 Nm between the torsion bar and the stabilizer bar and between the torsion bar and the suspension strut to resolve.

