

Key position #1

Press steering wheel back button until you are on the odometer screen..

Press Telephone Pick up and OK steering wheel buttons same time until the cluster menu changes

(about 5 seconds)

Select Assyst Plus with the up down arrows buttons on the steering wheel then press OK..

Select Full **Service** with up down arrows and press OK

Select Confirm Service and press OK

Select Confirm and press OK..

Now cycle the key off and on and check in the customer Assyst menu that the reset was successful..