

Document 215% Continuous document Validity off Page 1 of 1

GF54.15-P-1256-11GR Fuse assignment of fuse box in interior compartment on passenger's side GF

*F32/4 Interior prefuse box*

**i** When "ATO" and "MAXI" fuses are changed, they must always be replaced with fuses that comply with the Mercedes-Benz standard: "MBN10153-2".

**i** The designations 250 to 257 relate to the electrical fuses f250 to f257 respectively.

F32/4

Document 240% Continuous document Validity off Page 1 of 1

P54.15-3343-06

Fuse	Circuit	Line ID (fused line)	Fused function	Rating in amperes (A)
f250	30	4.0 RDWH	● SAM control unit (N10)	40
f251	30	4.0 RDWH	● SAM control unit (N10)	40
f252	30	4.0 RDWH	● SAM control unit (N10)	40
f253	30	2.5 RDWH	● Left front door control unit (N69/1)	30
f254	30	2.5 RDWH	● Left rear door control unit (N69/3)	30
f255	30	25.0 RD	● Battery compartment prefuse box (F33)	200
f256	30	42.0 RD	● Rear fuse box (F4)	150
f257	30	16.0 RD	<b>Valid for diesel engine:</b> ● PTC heater booster (R22/3)	150