

Flagship Motorcars
 385 Broadway, Rte. 1 North
 Lynnfield, MA 01940
 781-596-9700
 www.herbchambers.com



Our Other Mercedes-Benz Locations:

Mercedes-Benz of Natick
 253 North Main Street
 Natick, MA 01760
 508-655-5350

Mercedes-Benz of Boston
 259 McGrath Highway
 Somerville, MA 02145
 617-666-4100

Mercedes-Benz

CUSTOMER NO. 95073	[REDACTED]	TAG NO. T274W	INVOICE DATE 12 Oct 2018	INVOICE NO. 313802
[REDACTED]	HOURLY RATE 0.00	LICENSE NO.	COLOR	NO. STOCK / STOCK NO.
[REDACTED]	YEAR/MAKE/MODEL 15 MERCEDES-BENZ TRUCK	PO NO.	MILEAGE IN 52787	MILEAGE OUT 52787
[REDACTED]	[REDACTED]	[REDACTED]	DELIVERY DATE 26 Feb 2015	IN SERVICE DATE
EMAIL ADDRESS email [REDACTED]	CELL PHONE [REDACTED]	SALES PERSON	R.O. DATE 09 Oct 2018	WAR EXP. 26 Feb 2015
TEL HOME [REDACTED]	TEL BUSINESS EXT. [REDACTED]	COMMENTS ENG:4.7_Liter_Twin_Turbo 8		

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A							
A CUSTOMER STATES THAT DRIVERS REAR WILL OPEN THE DOOR WITHOUT THE KEY BEING AROUND, PASSANGER REAR DOOR WILL AT TIMES DO THE SAME THING CAUSE: ELECTRICAL FAULT 541011 PERFORM QUICK TEST 3917 WSM (N/C) 1 099-730-45-00-28 DOOR LOCK (N/C) 540650 ON-BOARD POWER SUPPLY VOLTAGE MAINTAIN (WHEN CHECKING/ TESTING AND TROUBLESHOOTING) 3917 WSM (N/C) 724380 LOCK OF LEFT 2ND DOOR REPLACE (INSIDE DOOR PANEL REMOVED) 3917 WSM (N/C) 726420 INSIDE DOOR TRIM ON 2ND DOOR, LOCATION:..... REMOVE/INSTALL 3917 WSM (N/C)							
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE A:	0.00
DRIVER SIDE REAR DOOR WHEN OPEN ALARM GO OFF , PERFORMED TEST FOUND NO CODE , REPLACE DRIVER SIDE REAR DOOR LOCK , REASSEMBLE THE VEHICLE ROAD TEST OK *****							
B							
B CUSTOMER STATES THAT AC SEEMS TO BE HISSING FROM THE CENTER OF THE DASHBOARD 20 HEATING/COOLING 3917 ISP (N/C)							
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE B:	0.00
PERFORMED A/C RECOVERY / RECHARGE PER SHOP FORMAN . ROAD TEST OK *****							
C**							
C** CUSTOMER STATES THAT KEYLESS ENTRY FOR MAINLY THE DRIVERS DOOR WILL NOT OPEN OR LOCK EVERYTIME EVEN IF KEY FOB IS RIGHT NEAR THE DOOR CAUSE: ELECTRICAL FAULT 724390 LOCK OF RIGHT 2ND DOOR REPLACE(INSIDE DOOR PANEL REMOVED)							

<input type="checkbox"/> CASH <input type="checkbox"/> VISA <input type="checkbox"/> AMEX <input type="checkbox"/> CHECK CK NO. [] <input type="checkbox"/> MASTERCARD <input type="checkbox"/> CHARGE <input type="checkbox"/> OTHER	<table border="1"> <thead> <tr> <th>DESCRIPTION</th> <th>TOTALS</th> </tr> </thead> <tbody> <tr><td>LABOR AMOUNT</td><td></td></tr> <tr><td>PARTS</td><td></td></tr> <tr><td>GAS, OIL, LUBE</td><td></td></tr> <tr><td>SUBLET REPAIRS</td><td></td></tr> <tr><td>MISCELLANEOUS CHARGES</td><td></td></tr> <tr><td>TOTAL CHARGES</td><td></td></tr> <tr><td>LESS DISCOUNT/INSURANCE</td><td></td></tr> <tr><td>SALES TAX</td><td></td></tr> <tr><td>PLEASE PAY THIS AMOUNT</td><td></td></tr> </tbody> </table>	DESCRIPTION	TOTALS	LABOR AMOUNT		PARTS		GAS, OIL, LUBE		SUBLET REPAIRS		MISCELLANEOUS CHARGES		TOTAL CHARGES		LESS DISCOUNT/INSURANCE		SALES TAX		PLEASE PAY THIS AMOUNT	
DESCRIPTION	TOTALS																				
LABOR AMOUNT																					
PARTS																					
GAS, OIL, LUBE																					
SUBLET REPAIRS																					
MISCELLANEOUS CHARGES																					
TOTAL CHARGES																					
LESS DISCOUNT/INSURANCE																					
SALES TAX																					
PLEASE PAY THIS AMOUNT																					
<p><i>THANK YOU FOR CHOOSING FLAGSHIP MOTORCARS</i></p> <p>_____ Customer Signature</p> <p>Environmental Compliance <small>Federal and state laws require that all hazardous waste (oil, solvents, anti-freeze, etc.) must be disposed of by a licensed contractor in an environmentally safe manner. Any charges for environmental compliance reflect our conformity to federal and state law in addition to our concern for the preservation of the environment.</small></p>																					

Flagship Motorcars
 385 Broadway, Rte. 1 North
 Lynnfield, MA 01940
 781-596-9700
 www.herbchambers.com



Our Other Mercedes-Benz Locations:

Mercedes-Benz of Natick
 253 North Main Street
 Natick, MA 01760
 508-655-5350

Mercedes-Benz of Boston
 259 McGrath Highway
 Somerville, MA 02145
 617-666-4100

Mercedes-Benz

CUSTOMER NO. 95073	[REDACTED]	TAG NO. T274W	INVOICE DATE 12 Oct 2018	INVOICE NO. 313802
[REDACTED]	HOURLY RATE 0.00	LICENSE NO.	COLOR	NO. STOCK / STOCK NO.
[REDACTED]	YEAR/MAKE/MODEL 15 MERCEDES-BENZ TRUCK	PO NO.	MILEAGE IN 52787	MILEAGE OUT 52787
[REDACTED]	VEHICLE IDENTIFICATION NO. [REDACTED]		DELIVERY DATE 26 Feb 2015	IN SERVICE DATE
EMAIL ADDR email [REDACTED]	CELL PHONE [REDACTED]	SALES PERSON	R.O. DATE 09 Oct 2018	WAR EXP. 26 Feb 2015
[REDACTED]	TEL BUSINESS EXT.	COMMENTS ENG:4.7_Liter_Twin_Turbo 8		

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
		3917	WSM				(N/C)
	1	099-730-46-00	DOOR LOCK				(N/C)
	726420	INSIDE DOOR TRIM ON 2ND DOOR, LOCATION:..... REMOVE/INSTALL					(N/C)
		3917	WSM				(N/C)
PARTS:		0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE C: 0.00
PASSENGER SIDE REAR DOOR WHEN OPEN ALARM GO OFF , PERFORMED TEST FOUND NO CODE , REPLACE PASSENGER SIDE REAR DOOR LOCK , REASSEMBLE THE VEHICLE ROAD TEST OK							

D**	LOANER CAR						
		999	ILS				(N/C)
PARTS:		0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE D: 0.00

<input type="checkbox"/> CASH <input type="checkbox"/> VISA <input type="checkbox"/> AMEX <input type="checkbox"/> CHECK CK NO. [] <input type="checkbox"/> MASTERCARD <input type="checkbox"/> CHARGE <input type="checkbox"/> OTHER	<table border="1"> <thead> <tr> <th>DESCRIPTION</th> <th>TOTALS</th> </tr> </thead> <tbody> <tr> <td>LABOR AMOUNT</td> <td>\$ 0.00</td> </tr> <tr> <td>PARTS</td> <td>\$ 0.00</td> </tr> <tr> <td>GAS, OIL, LUBE</td> <td>\$ 0.00</td> </tr> <tr> <td>SUBLET REPAIRS</td> <td>\$ 0.00</td> </tr> <tr> <td>MISCELLANEOUS CHARGES</td> <td>\$ 0.00</td> </tr> <tr> <td>TOTAL CHARGES</td> <td>\$ 0.00</td> </tr> <tr> <td>LESS DISCOUNT/INSURANCE</td> <td>\$ 0.00</td> </tr> <tr> <td>SALES TAX</td> <td>\$ 0.00</td> </tr> <tr> <td>PLEASE PAY THIS AMOUNT</td> <td>\$ 0.00</td> </tr> </tbody> </table>	DESCRIPTION	TOTALS	LABOR AMOUNT	\$ 0.00	PARTS	\$ 0.00	GAS, OIL, LUBE	\$ 0.00	SUBLET REPAIRS	\$ 0.00	MISCELLANEOUS CHARGES	\$ 0.00	TOTAL CHARGES	\$ 0.00	LESS DISCOUNT/INSURANCE	\$ 0.00	SALES TAX	\$ 0.00	PLEASE PAY THIS AMOUNT	\$ 0.00
DESCRIPTION	TOTALS																				
LABOR AMOUNT	\$ 0.00																				
PARTS	\$ 0.00																				
GAS, OIL, LUBE	\$ 0.00																				
SUBLET REPAIRS	\$ 0.00																				
MISCELLANEOUS CHARGES	\$ 0.00																				
TOTAL CHARGES	\$ 0.00																				
LESS DISCOUNT/INSURANCE	\$ 0.00																				
SALES TAX	\$ 0.00																				
PLEASE PAY THIS AMOUNT	\$ 0.00																				
THANK YOU FOR CHOOSING FLAGSHIP MOTORCARS _____ Customer Signature Environmental Compliance <small>Federal and state laws require that all hazardous waste (oil, solvents, anti-freeze, etc.) must be disposed of by a licensed contractor in an environmentally safe manner. Any charges for environmental compliance reflect our conformity to federal and state law in addition to our concern for the preservation of the environment.</small>																					

CUSTOMER COPY