

A C/S GETTING A WIND NOISE COMING FROM THE FRONT TWO WINDOWS WHILE DRIVING. C/S NOISE GETS LOUDER WHILE DRIVING FREEWAY SPEEDS
 941017 W08 NOISES FROM AT BODY LOCALIZE TECHNICIAN TEST DRIVE:

 DEPARTURE:.....
 ARRIVAL:..... KM AT
 START:

Tech(s): 2012
 253-725-60-00 1 GLASS N/C
 253-725-59-00 1 GLASS N/C
 205-737-21-00 2 INSULATION N/C
 724965 W08 CRANK WINDOW OF 1ST DOOR ON LEFT REPLACE N/C

Tech(s): 2012
 724985 W08 CRANK WINDOW OF 1ST DOOR ON RIGHT REPLACE N/C

Tech(s): 2012
 Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line A: 0.00
 Story: 257 72N0139 VERIFIED COMPLAINT. FOLLOWED LI72.10-P-062500.
 TAPED OFF BODY AND ROAD TESTED. FOUND NOISE STILL EXISTS.
 REPLACED BOTH FRONT SIDE WINDOWS WITH ACOUSTIC GLASS PER LI.
 ROAD TESTED AND VERIFIED ELIMINATION OF NOISE

B WINDOW TINT
 99 IWO SUBLET--TINT,DENT REMOVAL,WHEEL REPAIR,WINDSHIELD REPLACEMENT,PAINT REPAIR,INTERIOR REPAIR N/C

Tech(s): 2012
 Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line B: 0.00

C MERCEDES-BENZ LOANER VEHICLE (VALUE OF \$69.00 PER DAY RENTAL) FOR CUSTOMER SATISFACTION. FEE OF \$15.50 PER VISIT FOR FUEL USAGE AND APPEARANCE MAINTENANCE WITH MAXIMUM OF \$60.00 N/C
 ATMB IP MERCEDES-BENZ LOANER VEHICLE (VALUE OF \$69.00 PER DAY RENTAL) FOR CUSTOMER SATISFACTION. FEE OF \$15.50 PER VISIT FOR