

Work Order: 606625  
 Last Name: ~~XXXXXXXXXX~~  
 First Name: ~~XXXXXXXXXX~~  
 Company: BMC  
 VIN: WDCGG5K~~XXXXXXXXXX~~  
 License: SC  
 Year: 15  
 Technician: Manager  
 Odometer: 65750  
 Date: 4/16/19 7:56 AM



WDCGG5HB0FG429940

Mercedes-Benz 2010-15 204 (GLK)

Front : Left

Actual	Before	Specified Range
-1.0°*	-1.0°*	-0.6° 0.1°
9.4°	9.4°	
0.07°	0.07°	0.00° 0.17°
13.3°	13.3°	
12.3°	12.3°	
		-2.00° -1.00°

Front : Right

Actual	Before	Specified Range
-0.6°*	-0.6°*	-0.6° 0.1°
9.3°	9.3°	
0.09°	0.18°*	0.00° 0.17°
13.5°	13.5°	
12.9°	12.9°	
		-2.00° -1.00°

Camber  
 Caster  
 Toe  
 SAI  
 Included Angle  
 Turning Angle Diff.

Front

	Actual	Before	Specified Range
Cross Camber	-0.4°	-0.3°	-0.4° 0.4°
Cross Caster	0.1°	0.1°	-0.5° 0.5°
Cross SAI	-0.2°	-0.2°	
Total Toe	0.16°	0.25°	0.00° 0.34°
Cross Turn Diff.			

Rear : Left

Actual	Before	Specified Range
-1.1°	-1.1°	-1.6° -0.6°
0.22°	0.34°*	0.08° 0.32°

Rear : Right

Actual	Before	Specified Range
-1.3°	-1.3°	-1.6° -0.6°
0.19°	0.50°*	0.08° 0.32°

Camber  
 Toe

Rear

	Actual	Before	Specified Range
Cross Camber	0.2°	0.2°	-0.5° 0.5°
Total Toe	0.41°	0.85°*	0.27° 0.51°
Thrust Angle	0.02°	-0.08°	-0.25° 0.25°

\* This value is not within specification. Tire wear, handling and safety problems may result.