

Tire Manufacturer's Puncture Repair Recommendations

Manufacturer/ Brand	Speed Rating	Multiple Repair Locations
BFGoodrich	Maintained	3 repairs, minimum 90° apart
Bridgestone	Voided	2 repairs, must be a minimum of 16" apart
Continental*	Maintained	Repairs cannot overlap
Cooper	Voided	Repairs cannot overlap
Dick Cepek	Voided	Repairs cannot overlap
Dunlop	Maintained**	Repairs cannot overlap
		1 repair, H and above
Falken	Voided	Repairs cannot overlap
Firestone	Voided	2 repairs, must be a minimum of 16" apart
Fuzion	Voided	2 repairs, must be a minimum of 16" apart
General*	Maintained	Repairs cannot overlap
Goodyear	Maintained**	Repairs cannot overlap
		1 repair, H and above
Hankook	Voided	Repairs cannot overlap
Kumho	Voided	2 repairs, minimum 180° apart
Laufenn	Maintained	Repairs cannot overlap
Michelin	Maintained	3 repairs, minimum 90° apart
Nexen	Maintained	Repairs cannot overlap
Pirelli V and Above	Repair Not Endorsed by Pirelli	1 repair
H and Below	Maintained	
Power King	Voided	Repairs cannot overlap
RIKEN	Maintained	3 repairs, minimum 90° apart
Sumitomo	Voided	Repairs cannot overlap

Toyo H and Above	Reduced to H. Voided if more than one repair.	4 repairs, minimum 90° apart
Below H	Maintained. Voided if more than one repair.	4 repairs, minimum 90° apart
Uniroyal	Maintained	3 repairs, minimum 90° apart*
Vredestein V and Above	Repair Not Endorsed by Vredestein	2 repairs
H and Below*	Reduce 1 speed rating per repair	
Yokohama	Voided	Repairs cannot overlap
<p>*Voids materials, workmanship and tread wear-out warranties. **Only 1 repair permitted to retain H and above speed ratings.</p>		