

LABOUR

Item	Description	Qty	Value	Value (40% off)	Value (\$)	Value \$ (40% off)
1101001	Oil loss from engine determine	0				
1130003	Cylinder sealing/leakage check (access holes exposed for access)	0,6	240	144	\$65,40	\$39,24
1132102	Cylinders (all) inspect with light probe (access holes exposed for access)	0,6	240	144	\$65,40	\$39,24
1501103	Valve covers (all) remove / install, seal	3,1	1240	744	\$337,87	\$202,72
1579003	Cylinder heads (both) remove / install	12,7	5080	3048	\$1.384,20	\$830,52
3306303	Crankshaft radial seal at rear on output end replace (crankshaft radial oil seal exposed for access)	0,6	240	144	\$65,40	\$39,24
27202801	Automatic transmission remove / install veh. With transmission 722.6	6,6	2640	1584	\$719,35	\$431,61
27498001	Pilot bushing in the electrohydraulic control unit remove / install / seal, replace if necessary (after check)	0,4	160	96	\$43,60	\$26,16
27528501	Replace transmission oil filter + oil pan seal	1,2	480	288	\$130,79	\$78,47
46540001	Fluid reservoir for power steering remove / install and, if necessary, replace	1,6	640	384	\$174,39	\$104,63
46390004	power steering pump remove / install	1,9	760	456	\$207,08	\$124,25
46406005	power steering pump exchange	2	800	480	\$217,98	\$130,79
46361002	Power steering exchange	5,3	2120	1272	\$577,66	\$346,59
33143202	Control arm on lower left side of front axle remove / install and, if necessary, replace	3,1	1240	744	\$337,87	\$202,72
33143302	Control arm on lower right side of front axle remove / install and, if necessary, replace	3,1	1240	744	\$337,87	\$202,72
33143802	Control arm on upper left side of front axle remove / install and, if necessary, replace	0,9	360	216	\$98,09	\$58,86
33144002	Control arm on upper right side of front axle remove / install and, if necessary, replace	0,9	360	216	\$98,09	\$58,86
33149802	Control arm on upper left side of front axle remove / install and, if necessary, replace (front axle removed)	0,4	160	96	\$43,60	\$26,16
33150002	Control arm on upper right side of front axle remove / install and, if necessary, replace (front axle removed)	0,4	160	96	\$43,60	\$26,16
33775002	Front final-drive unit remove / install	2,7	1080	648	\$294,28	\$176,57
33767801	input flange on front final drive unit pinion gear remove / install / seal, replace if necessary (driveshaft disconnected at flange)	0,6	240	144	\$65,40	\$39,24
40650001	Wheel alignment perform	0,8	320	192	\$87,19	\$52,32
40671101	Extra work for: alignment check: camber / caster at left rear axle half adjust	0,3	120	72	\$32,70	\$19,62
40671201	Extra work for: alignment check: camber / caster at right rear axle half adjust	0,3	120	72	\$32,70	\$19,62
40671601	Extra work for: alignment check: camber / caster at left front axle half adjust	0,4	160	96	\$43,60	\$26,16
40671701	Extra work for: alignment check: camber / caster at right front axle half adjust	0,4	160	96	\$43,60	\$26,16
20114002	Coolant with antifreeze replace and check for leaks	1	400	240	\$108,99	\$65,40

20541001	Expansion reservoir for coolant remove / install and, if necessary, replace	1	400	240	\$108,99	\$65,40
40145001	Road wheels (all) remove / install	0,9	360	216	\$98,09	\$58,86
42142002	Fluid in hydraulic brake system replace	0,8	320	192	\$87,19	\$52,32
42273102	Brake rotors on front axle remove / install and, if necessary, replace (with brake pads removed)	0,8	320	192	\$87,19	\$52,32
42288102	Brake rotors on rear axle remove / install and, if necessary, replace (with brake pads removed)	0,8	320	192	\$87,19	\$52,32
32106202	Shock absorbers (all (2)) of 2nd vehicle axle remove / install and, if necessary, replace	3,1	1240	744	\$337,87	\$202,72
TOTAL			AED 23.720	AED 14.232	\$6.463,22	\$3.877,93