BlueDriver. Scan Report

2007 Mercedes-Benz M-Class V6, 3.5L

4JGBB86E47A247851 Odometer: 156,398 miles

10 Pending Codes

- **P0203** Cylinder 3 Injector "A" Circuit
- P0010 "A" Camshaft Position Actuator Control Circuit/Open Bank 1
- P0300 Random/Multiple Cylinder Misfire Detected
- P0302 Cylinder 2 Misfire Detected
- P0447 EVAP System Vent Control Circuit Open
- **P0202** Cylinder 2 Injector "A" Circuit
- P0100 Mass or Volume Air Flow Sensor "A" Circuit
- P0013 "B" Camshaft Position Actuator Control Circuit/Open Bank 1
- P0301 Cylinder 1 Misfire Detected
- P0303 Cylinder 3 Misfire Detected

4 Upper Control Panel Codes

B1036 Undervoltage detection . Undervoltage is not detected until after 5 s and a voltage NOT PRESENT of < 9.5 V.

B1038 Not Relevant!

B1020 No CAN message was received from control unit N73 (EIS [EZS] control unit).

B1021 No CAN message was received from control unit A1 (Instrument cluster).

3 Door Control Module - Front Left Codes

B1002 The supply voltage of control unit DCM-FL is too low (undervoltage).

B1012 No description available

NOT PRESENT

B1015 No description available

NOT PRESENT

2 Door Control Module - Front Right Codes

B1002 The supply voltage of control unit DCM-FR is too low (undervoltage).

B1014 S85/6 (Right interior CL [ZV] switch) : The component remains in the switched ^{NOT PRESENT} status (contact sticking) or has Short circuit to ground.

2 Airbag Codes

B11C0 A component of control unit WSS is defective or not calibrated.

B11C3 A component of control unit WSS may possibly be defective or not calibrated. PRESENT

2 Roof Control Module Codes

B1010 The voltage was less than 9,0 V during 5 s.

B1600 No description available

1 Weight Sensing System Code

B1A14 No description available PRESENT

10 Motor Electronics Codes

P0633 Combustion misfiring of cylinder 1 has been detected.

P0641 Combustion misfiring of cylinder 3 has been detected.

P0649 Combustion misfiring of cylinder 2 has been detected.

PRESENT

PRESENT

P0311 The fuel injector (cylinder 3) has an electrical fault or an open circuit.

P0319 The fuel injector (cylinder 2) has an electrical fault or an open circuit.

P0067 The actuator "Exhaust camshaft" (cylinder bank 1) has an electrical fault or an open circuit.

P0279 The actuator "Intake camshaft" (cylinder bank 1) has an electrical fault or an open circuit.

P0959 The shutoff valve of the activated charcoal canister has an open circuit.

P2182 Mass air flow sensor 1 has a malfunction.

PRESENT

P0629 Combustion misfiring has been detected.

PRESENT

Disclaimer: This information is provided without warranty and is subject to the Terms of Use posted at www.bluedriver.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.