

2009 Mercedes-Benz M-Class

4JGBB56E59A508972

Odometer: 141,053 mi

0 Confirmed Codes

0 Pending Codes

0 Permanent Codes

1 OCP - Overhead control panel Code

B1201 B38/2 (Rain/light sensor) : Communication fault / Open circuit
PRESENT

2 COMAND or AUDIO Codes

U1A00 Check report for description.
PRESENT

B210D The power supply is too low.
NOT PRESENT

3 RevETR-LF - Left front reversible emergency

C1261 The supply voltage of the control unit is too low (undervoltage).
NOT PRESENT

C1061 Control unit A76 (Left front reversible emergency tensioning retractor) is
NOT PRESENT defective.

C134D CAN message from control module N2/7 (Restraint systems control unit) is faulty.
NOT PRESENT S68/1 (Seat belt buckle and seat belt warning switch, driver)

3 RevETR-RF - Right front reversible emergency

C1261 The supply voltage of the control unit is too low (undervoltage).
NOT PRESENT

C1061 Control unit A76/1 (Right front reversible emergency tensioning retractor) is
NOT PRESENT defective.

C134D CAN message from control module N2/7 (Restraint systems control unit) is faulty.
NOT PRESENT S68/1 (Seat belt buckle and seat belt warning switch, driver)

1 REAR SAM - Rear signal acquisition and actuation

B1232 Fehler: Motor Tuer Fond rechts, Schluss nach GND oder Openload
NOT PRESENT

1 SAM-F - Signal acquisition and actuation module front

B100F Sidemarker links defekt
PRESENT

2 ME 9.7 - Motor electronics 9.7 Codes

P0521 The charge movement flap (cylinder bank 1) has a malfunction.
PRESENT

P0515 The signal of oxygen sensor 2 (cylinder bank 2) is shifted towards "Rich".
NOT PRESENT

Disclaimer: This information is provided without warranty and is subject to the Terms of Use posted at www.bluedriver.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.