AN31.10-P-8080GQ Retrofit trailer hitch 19.06.2019

Model 166.0

up to model year 2016

with code 460 (Canada version) except code 498 (Japanese version) except code 830 (China version) except code Z04 (Light armoring)

except code Z05 (B5 armoring on special protection version)

Model 166.0

up to model year 2016 with code 494 (US version)

except code 498 (Japanese version) except code 830 (China version) except code Z04 (Light armoring)

except code Z05 (B5 armoring on special protection version)

Model 166.0

up to model year 2016

with code 496 (Mexico version) except code 498 (Japanese version) except code 830 (China version) except code Z04 (Light armoring)

except code Z05 (B5 armoring on special protection version)

Shown with code 494 (USA version)

1 Trailer hitch



P31.10-3391-06

8 Cross member



	Risk of death caused by vehicle slipping or toppling off of the lifting platform.	Align vehicle between vehicle lift columns and position the four support plates at the vehicle lift support points specified by the vehicle manufacturer.	AS00.00-Z-0010-01A
	Notes on self-locking nuts and bolts		AH00.00-N-0001-01A
	Notes on installing a trailer hitch		AH31.10-P-1000-02CW
	Information on preventing damage to electronic components due to electrostatic discharge		AH54.00-P-0001-01A
X	Remove		
1	Print out the detailed installation instructions and give them to the customer	For do-it-yourself installation by the customer.	
2 ►AR	Remove paneling at bottom of right B-pillar		AR68.30-P-4700GQ
3	Detach front SAM control unit and place to one side with electrical connectors still connected		
AR ₄	Damasua riaht faant aaat		AR54.21-P-1254GQ
4 № AR 5	Remove right front seat		AR91.10-P-1000GQ
o ⊯≅AR	Remove center console		AR68.20-P-2000GQ
6	Remove left front floor covering		
FAR 7	Remove right rear seat cushion		AR68.20-P-2050GQ
FAR	<u> </u>		AR91.12-P-1020GQA
8 ⊯AR	Remove backrest on right in rear		AR91.12-P-1620GQA
9 AR	Disconnect battery ground line		AR54.10-P-0003GZ
10	Detach rear fuse box and place to one side		AR34.10-P-0003GZ
	with electrical connectors still connected		
F AR	D 1100 11 10 1 1100		AR54.15-P-1261GQ
11	Remove additional battery and additional battery bracket		
⊯ AR		Model 166.0 up to model year 2016 except code B03 (ECO start/stop function), except code ME05 (HYBRID DRIVE 80KW VARIANT (INCLUDING PLUGIN))	AR54.10-P-0121GQ
S AR		Model 166.0 up to model year 2016 with code B03 (ECO start/stop function)	AR54.10-P-0007GQA
12 ► AR	Remove side paneling in right side of trunk		AR68.30-P-4800GQ
13	Loosen trim for spare tire well		
AR AR			AR68.30-P-4620GQ
		Model 166.0 up to model year 2016 with code 489 (AIRmatic) Do not remove the AIRmatic central reservoir.	
14	In the EPC in DG 99, check whether the	If incompatible	
	electric fan fitted in accordance with the vehicle equipment can be used for retrofitting the trailer hitch (1)		
		↓	
		Remove electric fan and replace with an electric fan compatible with trailer hitch (1).	
AR		Model 166.0 with engine 157, 278 up to model year 2016	AR20.40-P-5050MLJ
AR		Model 166.0 with engine 276, 642, 651 up to model year 2016	AR20.40-P-5050GQ
15	Detach electrical connector from radiator shutters actuator, insulate it and then strap it down	Model 166.0 with engine 642, 651 up to model year 2016 except code 430 (On & Off-road package) The electrical connector is no longer	
16	Remove vacuum line with connection to radiator shutters actuator from brake booster	required. Model 166.0 with engine 642, 651 up to model year 2016 except code 430 (On & Off-road package)	
		The removed vacuum line is no longer required.	
17	Remove AdBlue® tank		

⊯ AR		Model 166.0 with engine 642, 651 up to model year 2016 with code U42 (BlueTEC (SCR) diesel exhaust treatment) or code U77 (BlueTEC (SCR) diesel exhaust treatment)	AR14.40-P-2014GQ
⚠ Warning	Risk of injury. Skin or eye injuries may result when handling hot or glowing objects. Unhook rear muffler from spacer	Wear protective gloves, protective clothing and safety glasses, if necessary.	AS00.00-Z-0002-01A
⚠ Warning	Risk of injury. Skin or eye injuries may result when handling hot or glowing objects.	Wear protective gloves, protective clothing and safety glasses, if necessary.	AS00.00-Z-0002-01A
⚠ Caution	Risk of injury caused by scraping or cutting body parts on sharp vehicle parts	Always wear protective gloves when working on or near sharp and non-deburred vehicle parts. Deburr repair panels.	AS00.00-Z-0017-01A
19	Remove heat shield of rear muffler		
20	Remove cross member (8) for rear bumper		
l≆ ² AR		i The cross member (8) is no longer required.	AR88.20-P-2250GQ
21	Remove fuel tank	- oquiloui	
⊯ AR		Model 166.023/024 up to model year 2016 except code 915 (Fuel tank with increased capacity)	AR47.10-P-4100GQ
X	Install	The fuel tank is no longer required.	
22	Retrofit mechanical detachable parts for trailer hitch (1)		AN31.11-P-8080-05GQ
		Screw/bolt, reinforcement arm to vehicle floor	*BA31.11-P-1001-01G
		Bolt/nut, trailer hitch/reinforcement plate to rear center section	
		Screw/bolt, trailer hitch to reinforcement	*BA31.11-P-1004-01G
23 ⊯AR	Install AdBlue® tank	Model 166.0 with engine 642, 651 up to model year 2016 with code U42 (BlueTEC (SCR) diesel exhaust treatment) or code U77 (BlueTEC (SCR) diesel exhaust treatment)	AR14.40-P-2014GQ
24	Install fuel tank with increased capacity		
IS AR		Model 166.023/024 up to model year 2016 except code 915 (Fuel tank with increased capacity) i New heat shields for the fuel tank with	AR47.10-P-4100GQ
		increased capacity must be used.	
25 26	Retrofit trailer hitch control unit		AN31.19-P-8080-05GQ
26	Retrofit trailer hitch wiring harness Notes on the use of paint scraping nuts on ground connections		AN31.19-P-8100-05GQ AH00.19-P-1000-20A
		Nm Right rear center section ground point	*BA00.19-P-1006-01G
		Nm Trailer hitch ground point	*BA00.19-P-1007-01G
		Left footwell ground point	*BA00.19-P-1016-01G
		New passenger car wiring harness repair kit	*220589049900
		Wiring harness repair kit, basic	*000589139900
27	Add bumper cutout	, , , ,	AN31.11-P-8080-02GQ
28	Install new impact absorber between rear bumper and trailer hitch (1)		
29	Install new vacuum line without connection to radiator shutter actuator	Model 166.0 with engine 642, 651 up to model year 2016 except code 430 (On & Off-road package)	
30	Install remaining parts	. ,	
	Update Vehicle Documentation (VeDoc)		
31	Delete special equipment from on-line vehicle data card	Model 166.0 with engine 642, 651 up to model year 2016 except code 430 (On & Off-road package)	
32	Enter special equipment into the on-line	i Code 2U1 (Radiator shutters) Code 550 (Trailer hitch)	
	vehicle data card	, ,	
33	Enter special equipment into the on-line vehicle data card	Model 166.023/024 up to model year 2016 except code 915 (Fuel tank with increased capacity) i Code 915 (Fuel tank with increased capacity)	

34	Attach note "Trailer hitch retrofitted as per AN31.10-P-8080GQ" under field organization		
	texts to design group 31, design group 54 and design group 88.		
35	Attach note "Trailer hitch retrofitted as per AN31.10-P-8080GQ" under field organization texts for design group 47.	Model 166.023/024 up to model year 2016 except code 915 (Fuel tank with increased capacity)	
36	Attach "Trailer hitch retrofitted as per AN31.10-P-8080GQ" note under field organization texts for design group 50.	Insofar as the electric fan was replaced.	
37	Attach "Trailer hitch retrofitted as per AN31.10-P-8080GQ" note under field organization texts for design group 50.	Model 166.0 with engine 642, 651 up to model year 2016 except code 430 (On & Off-road package)	
38	Connect diagnostic system and select vehicle using vehicle identification number (VIN)		
⊯ AD			AD00.00-P-2000-04A
39	Carry out variant coding using software calibration number (SCN)	i SAM control unit Instrument cluster Head unit Central gateway in electronic ignition lock control unit ESP® control unit	
40	Carry out variant coding using software calibration number (SCN)	Model 166.0 with engine 642, 651 up to model year 2016 except code 430 (On & Off-road package) i CDI control unit	
41	Carry out variant coding using software calibration number (SCN)	Model 166.0 up to model year 2016 with code 218 (Reversing camera) i Backup camera	
42	Carry out variant coding using software calibration number (SCN)	Model 166.0 up to model year 2016 with code 22P (Lane package) i Multifunction camera	
43	Carry out variant coding using software calibration number (SCN)	Model 166.0 up to model year 2016 with code 23P (Driving Assistance package Plus) i Stereo multifunction camera Chassis gateway control unit	
44	Carry out variant coding using software calibration number (SCN)	Model 166.0 up to model year 2016 with code 235 (Active Parking Assist with PARKTRONIC)	
45	Carry out variant coding using software calibration number (SCN)	Model 166.0 up to model year 2016 with code 501 (360° camera) i 360° camera control unit	
46	Carry out variant coding using software calibration number (SCN)	Model 166.0 up to model year 2016 with code 489 (AIRmatic) AIRMATIC control unit	
47 ⊯≃AD	Disconnect diagnostic system		AD00.00-P-2000-04A
<u> </u>	Check		
48	Perform function check on trailer hitch socket		AN31.19-P-8100-06GQX
48 49	Check ball neck for proper operation	i See the operator's manual for the exact operation steps.	AND 1. 19-7-0 100-00GQX

Nm Ground points

Number	Designation	·		Model 166	
BA00.19-P-1006-01G	Right rear center section ground point	W7	Nm	10	

Nm Ground points

Number	Designation			Model 166
BA00.19-P-1007-01G	Trailer hitch ground point	W7/9	Nm	10

Nm Ground points

Number	Designation			Model 166
BA00.19-P-1016-01G	Left footwell ground point	W15/2	Nm	10

Nm Trailer coupling mechanism


Number	Designation		Model 166
BA31.11-P-1001-01G	Screw/bolt, reinforcement arm to vehicle floor	Nm	66


Nm Trailer coupling mechanism

Number	Designation		Model 166
BA31.11-P-1002-01G	Bolt/nut, trailer hitch/reinforcement plate to rear center section	Nm	66

Nm Trailer coupling mechanism

Number	Designation		Model 166
BA31.11-P-1004-01G	Screw/bolt, trailer hitch to reinforcement arm	Nm	140





New passenger car wiring harness repair kit

Wiring harness repair kit, basic

Parts ordering note

Part no.	Designation	Quantity
KG 99 (siehe EPC)	Trailer hitch parts kit	1
Handelsüblich	Cable shoe, Ø 6 mm	1