

2005 E55 AMG

22 August 2015 Oil Level Sensor

94,658 miles

-Replaced oil level sensor. Old sensor giving intermittent failures.

-A006-193-59-28, engine oil level sensor, \$150

-Completed dual volt/amp meter to test fuel pumps for fuel filter blockage.

-Two each DROK meters @ \$16 each

-One project box, \$10

-A211-540-07-00, cable harness, \$15

-Total \$57

	-Volts	Amps
-Pump 1	13.6	3.9
-Pump 2	13.1	13.6





