BlueDriver. Scan Report

2016 MERCEDES-BENZ E-Class 3.5L V6

WDDHF8JB8GB313561 Odometer: 117,647 miles

1 Confirmed Code

P2540 Low Pressure Fuel System Sensor Circuit Range/Performance

1 Pending Code

P2540 Low Pressure Fuel System Sensor Circuit Range/Performance

1 Permanent Code

P2540 Low Pressure Fuel System Sensor Circuit Range/Performance

1 A90 - Control unit 'COLLISION PREVENTION ASSIST'

C10C8- System "COLLISION PREVENTION ASSIST" has triggered a warning.

00

CONFIRMED

1 N118 - Control unit 'Fuel pump' Code

P2540- The signal for the pressure sensor of the low-pressure fuel circuit is implausible.

00

CONFIRMED/P ENDING

3 A2 / A40/3 / A26/17 - Audio or COMAND Codes

B21A1- An internal control unit reset was performed.

00 CONFIRMED B156A- The connection with the control unit for telematics services cannot beestablished.

CONFIRMED

B159F- The Internet connection could not be established due to a problem with the network provider.

1 Generic Address Module Code

P06DA- No description available

00 PENDING

Disclaimer: This information is provided without warranty and is subject to the Terms of Use posted at www.bluedriver.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.