



# Mercedes-Benz Australia/Pacific Pty Ltd—Mercedes-Benz with OM651 Diesel Engines

---

**PRA No.** 2015/14509

**Date published** 8 Jan 2015

---

## Product description

Passenger cars and vans fitted with OM651 diesel engines

---

## Identifying features

Various passenger cars, Sprinter and Vito vans

## What are the defects?

The seal ring between the timing chain tensioner and the engine may leak oil.

## What are the hazards?

Leaking oil may result in a hazard to other road users and in extreme cases a fire risk.

## What should consumers do?

Letters will be sent to all owners of affected vehicles.

---

### Supplier

Mercedes-Benz Australia/Pacific Pty Ltd

### Traders who sold this product

Authorized Mercedes-Benz Dealers

### Where the product was sold

Nationally

### Dates available for sale

1 March 2014 - 30 November 2014

# Responsible regulator

Department of Infrastructure, Regional Development and Cities is the responsible regulator for this recall.

- ▶ [Information on vehicle recalls](#)
- ▶ [Report a vehicle safety or non-compliance issue](#)



## Australian Government

---

### Department of Infrastructure, Regional Development and Cities

**Product category** [Mercedes-Benz](#)

I want to... 

 [Receive email updates](#)

 [Subscribe to newsletter](#)

 [Report unsafe products](#)