



Mercedes-Benz Australia/Pacific Pty Ltd—Mercedes-Benz with OM651 Diesel Engines

PRA No. 2015/14509

Date published 8 Jan 2015

Product description

Passenger cars and vans fitted with OM651 diesel engines

Identifying features

Various passenger cars, Sprinter and Vito vans

What are the defects?

The seal ring between the timing chain tensioner and the engine may leak oil.

What are the hazards?

Leaking oil may result in a hazard to other road users and in extreme cases a fire risk.

What should consumers do?

Letters will be sent to all owners of affected vehicles.

Supplier

Mercedes-Benz Australia/Pacific Pty Ltd

Traders who sold this product

Authorized Mercedes-Benz Dealers

Where the product was sold

Nationally

Dates available for sale

1 March 2014 - 30 November 2014

Responsible regulator

Department of Infrastructure, Regional Development and Cities is the responsible regulator for this recall.

- ▶ [Information on vehicle recalls](#)
- ▶ [Report a vehicle safety or non-compliance issue](#)



Australian Government


Department of Infrastructure, Regional Development and Cities

Product category

[Mercedes-Benz](#)

I want to...



 [Receive email updates](#)

 [Subscribe to newsletter](#)

 [Report unsafe products](#)