



Mercedes-Benz Australia/Pacific Pty Ltd—Mercedes-Benz E and CLS Passenger cars

PRA No. 2015/14888
Date published 31 Aug 2015

Product description

E and CLS Passenger cars

Identifying features

Recall number: RC2144

Target: 7 vehicles

What are the defects?

A damaged seal may have been fitted to the secondary bulkhead in the engine compartment; this seal may come loose and partially fall into the engine compartment.

What are the hazards?

If the seal comes in contact with hot engine components this could result in a risk of fire.

What should consumers do?

A letter will be sent to the owners of affected vehicles.

Supplier

Mercedes-Benz Australia/Pacific Pty Ltd

Traders who sold this product

Authorised Mercedes-Benz Dealers.

Where the product was sold

Nationally

Dates available for sale

1 April 2015 - 1 May 2015

Responsible regulator

Department of Infrastructure, Regional Development and Cities is the responsible regulator for this recall.

- ▶ [Information on vehicle recalls](#)
- ▶ [Report a vehicle safety or non-compliance issue](#)



Australian Government

Department of Infrastructure, Regional Development and Cities


Product category

Mercedes-Benz

I want to...



 [Receive email updates](#)

 [Subscribe to newsletter](#)

 [Report unsafe products](#)