



# Mercedes-Benz Australia/Pacific Pty Ltd—Mercedes-Benz E212 and CLS218

---

**PRA No.** 2015/14588  
**Date published** 10 Mar 2015

---

## Product description

Passenger cars, Models E212 and CLS218

---

## Identifying features

Recall RC2101  
2849 Vehicles Affected

## What are the defects?

The seal on the secondary bulkhead in the engine compartment may come loose and partially fall into the engine compartment.

## What are the hazards?

In extreme cases the seal may come in contact with hot engine components and could result in a risk of fire.

## What should consumers do?

Letters will be sent to all owners of affected vehicles.

---

### Supplier

Mercedes-Benz Australia/Pacific Pty Ltd

### Traders who sold this product

Authorised Mercedes-Benz Dealers

### Where the product was sold

Nationally

### Dates available for sale

1 July 2012 - 1 December 2014

# Responsible regulator

Department of Infrastructure, Regional Development and Cities is the responsible regulator for this recall.

- ▶ [Information on vehicle recalls](#)
- ▶ [Report a vehicle safety or non-compliance issue](#)



## Australian Government

---

## Department of Infrastructure, Regional Development and Cities

### Product category

[Mercedes-Benz](#)

I want to...



 [Receive email updates](#)

 [Subscribe to newsletter](#)

 [Report unsafe products](#)