

Vehicle information

Mercedes-Benz 202.029 C 280

VIN: WDBHA29G2YA847571

Diagnostics time: 2020/05/09 12:19

Mileage:

Path: Automatic selection > Left-hand steering > Sedan > Gasoline > 202.029 C 280 > Diagnosis > Auto scan >

Status report

System name	DTC counts	Status
ME2-SFI-Motor electronics 2	0	Pass
ETC-Electronic transmission control	0	Pass
ESP-Electronic stability program	01	Fault
AB-Airbag	0	Pass
ICM-Instrument cluster with maintenance interval display	0	Pass
ESM-Electronic selector module	01	Fault
EZS-Electronic ignition switch	0	Pass
OCP-Overhead control panel	0	Pass
LCP-Lower control panel	0	Pass
PSE-Pneumatic system equipment	0	Pass
SAM-Signal acquisition and actuation module	0	Pass
DCM1-Door control module front driver side	0	Pass
DCM2-Door control module front passenger side	0	Pass
DCM3-Door control module rear driver side	02	Fault
DCM4-Door control module rear passenger side	0	Pass
AUDIO	0	Pass
CTEL- Cellular telephone 1 (fixed installation or portable)(D2B)	0	Pass
CDC-CD changer	0	Pass
E-call [USA]-Emergency call system	0	Pass

AAC-Automatic air conditioning	0	Pass
--------------------------------	---	------

1. ESP-Electronic stability program — (01)

- 1.1. C1504-009 The system is deactivated. Steering Angle Sensor (SAS) has not been initialized.
MIL ON&Stored&Current

2. ESM-Electronic selector module — (01)

- 2.1. P1817-2 Component 'Reversing lamp' has a short circuit to battery.
Stored&Current

3. DCM3-Door control module rear driver side — (02)

- 3.1. B1010 The supply voltage of the control module is too low.
Stored&Current
- 3.2. B1155 Switch 'S21/3 (Left rear power window switch)' or switch S21/4 (Right rear power window switch) is operated for over 25s. Short circuit to ground
Stored&Current