Date Item	Cost	Miles	Notes
08/07/2007 Bike purchased new from Ducati dealership in Greenville, SC		0	
12/18/2007 Purchased bike from Tony Foster who claims to have performed 600mi service		1350	
01/06/2008 Oil/Filter change; Mobile1 Racing 4T 10W-40		1700	
06/01/2008 Installed Termignoni Slip-ons		3500	
08/01/08 Oil/Filter change; Mobile1 Racing 4T 10W-40		4860	
08/01/08 New Michelin Pilot Road Dual Compound Tires	\$120	4860 1 1 6547539-	001 Michelin Pilot 120/70/17
11/01/08 6,000 Mile Maintenance by Destination Motorcycle		6400	
12/27/08 DP ECU and full Termi's installed by NPR Ducati in Watkinsville, GA		6400	
07/11/09 New Michelin Pilot Power Dual Compound Tires	\$155		-001 Michelin Pilot 180/55/17
07/13/09 Oil/Filter change; Mobile1 Racing 4T 10W-40		8730 Mobil 1 Racing 4	T oil (3.5 liters) & AMSOIL Eao138 filter
07/13/09 Valve Lash checked; Fuel Filter; Spark Plugs; Cam Belt Adjusted		3 · · · · · · · · · · · · · · · · · · ·	
07/13/09 Throttle body balanced; compression check;			
07/13/09 Replaced valve guides under warranty; adjusted valves			
07/25/2009 Purchased bike from Louisville, KY		9231	
08/02/2009 New battery installed, chain lubed	\$135	10000	
08/03/2009 Cigarette lighter socket wiring kit installed	\$14	10000	
08/03/2009 Speedymoto Frame sliders installed	\$80	10000	
08/26/2009 Clear tank pads (Monsterparts)	\$30	10600	
08/26/2009 Front axle sliders (Speedymoto) installed	\$66		
08/26/2009 Handlebar sliders (Rizoma) installed	\$66		
09/17/2009 Rear Brake Pads (EBC HH Sintered) changed	\$40	11700	
10/03/2009 Dot 5 flushed and replaced with Dot 4 at Motor Cycle Center (Chicago)	\$70	11775	
01/10/2010 Air filter replaced - K&N	\$55		
03/21/2010 Oil changed (3.4 liters of Mobil 1 4T Racing Oil, K&N oil filter)	\$93	12213	
06/11/2010 4 Spark plugs (NGK DCPR8E) replaced	\$29	12660	
03/17/2011 Oil & oil filter changed (3.4 liters of Mobil 1 4T Racing Oil, K&N KN-153)	\$45	13890	
05/13/2011 14Tooth front sprocket installed	\$36	14400	
05/21/2011 Adjusted chain tension	-	14400 Was very lose	
··· · · · · · · · · · · · · · · · · ·		,	e valve with excessive clearance. Replaced shim.
			nd rear. Michelin Pilot Power 2CT.
06/08/2011 15k mile service - Valve check, belts, 2 tires	\$1,260	14800 Replaced belts.	
06/18/2011 Spark plugs replaced - NGK DCPR7E. Gapped.	\$12	15500	
06/24/2011 Throttle body balanced with SyncPro tool	· <u>-</u>	15613	
07/21/2011 OEM Air Filter installed	\$22	16150	
07/23/2011 Synced throttle bodies	· <u>-</u>	16400	
07/23/2011 Adjusted fuel trim to +2 with Technoresearch VDST	-	16400	
08/19/2011 Front brake fluid flush (Motul 5.1)	\$15	17002	
08/19/2011 Clutch fluid flush (Motul 5.1)	· <u>-</u>	17002	
08/19/2011 Cush drive bushings renewed with synthetic grease	\$5	17002	
08/20/2011 G2 Throttle Tamer	\$80	17004	
08/20/2011 Oil changed - Motul oil, Ducati oil filter	\$90	17004	
08/20/2011 Re-built front calipers and bled brakes again	-	17150	
08/20/2011 Brake pads for front (EBC Sintered HH FA244H)	\$76	17002	
	+		

		CA Cycle works. Cut down to 106 links.
08/24/2011 DID 525 X-Ring chain gold 108 link	\$125	17544 Used Harborfreight chain breaker/rivet tool.
10/31/2011 Front rotors changed	\$450	18619
11/05/2011 Steering head bearing - Shop fee to press on lower bearing	\$28	Vickery motorsports
11/05/2011 Steering head bearings replaced - Upgraded to tapered roller bearings	\$69	18500
12/12/2011 Throttle bodies synchronized	-	18619
12/23/2011 Bar end mirrors (silver)	\$100	18620 Oberon
12/28/2011 Fuel trim adjusted to +8 (was at +2)	-	18620
01/21/2012 K&N filter re-installed	-	18695