

Vehicle information

Benz 2008 251.165 R350 Gasoline

VIN: 4JGCB65E08A066239

Diagnostics time: 2022/03/14 15:42

Path: Automatic selection > Control unit > Drive > ME 9.7-Motor electronics 9.7 > Read codes >

Trouble codes

- | | |
|---------|---|
| 1. 0746 | Self-adaptation of the mixture formation for enleanment at idle speed for the right cylinder bank is below the permissible limit. (P0172)
Stored&Current |
| 2. 0750 | Self-adaptation of the mixture formation for enleanment at idle speed for the left cylinder bank is below the permissible limit. (P0175)
Stored&Current |
| 3. 2092 | The mixture in the right cylinder bank is too rich at idle speed.
Stored&Current |
| 4. 2096 | The mixture in the left cylinder bank is too rich at idle speed.
Stored&Current |