

Model 217
with code 308 (Refrigerated compartment in rear passenger compartment)

- 1 Phillips screws
- 2 Open refrigeration compartment



P86.61-2076-06

Warning	Risk of injury caused by fingers being jammed or pinched when removing, installing or aligning hoods, doors, trunk lid/rear-end door or sliding roof.	No parts of the body or limbs should be within the operating area when the components are moving.	AS00.00-Z-0011-01A
	Remove/install		
1	Open luggage compartment lid		
2	Remove Phillips screws (1)		
3	Disconnect electrical connector from refrigeration compartment (2)		
4	Remove refrigeration compartment (2)		
5	Install in the reverse order		