

Mercedes-Benz—S Class (type 221)—With Active Body Control (ABC) Suspension

PRA No.	Date published	23 Mar 2009
2009/10689		

What are the defect

Long term laboratory durability testing has revealed that the lower ball joint of the front struts on certain vehicles with ABC suspension could fracture after very high mileage when used on rough roads. Should this occur, normal steering of the vehicle will be impaired.

What are the hazard

Malfunction.

What should consumers c

Mercedes-Benz Australia/Pacific Pty Ltd will write to owners of all affected vehicles. If you have sold the vehicle, please contact Mercedes-Benz on telephone: 03 9566 9380, fax: 03 9566 6223 or via e-mail: campaigns@daimler.com

Supplier	Mercedes-Benz Australia/Pacific Pty Ltd
Where the product was sold	Nationally

Responsible regulator

Department of Infrastructure, Transport, Regional Development and Communications is the responsible regulator for this recall.

- ▶ [Information on vehicle recalls](#)
- ▶ [Report a vehicle safety or non-compliance issue](#)