# star bulletin





Date:	June 1, 2016
Order No.:	P-B-27.10/125a
Supersedes:	P-B-27.10/125, November 2013
Group:	27

### Revision a: Update on applicable models.

**SUBJECT:** MY-All, Transmission 725.0

### Launch Support for Automatic Transmission (9G-TRONIC)

#### Market Launch

The automatic transmission (9G-TRONIC) with code 421 (9-speed automatic transmission) will be used for the first time as of Fall 2014.

Important Note: When returning the automatic transmission (9G- TRONIC) major assemblies, the specified analysis sheet for automatic transmission (9G- TRONIC) has to be filled out and included with the automatic transmission. As always, major assemblies are returned via the warranty return process.

### **Technical Workshop and Product Support**

No repairs should be done on automatic transmission (9G-TRONIC). Only complete transmissions may be replaced. Parts can only be replaced after approval from workshop support. Until further notice a PTSS case must always be created and submitted to Product Technical Support.

The following documents must be included with the case:

- Quick test
- Control unit log with fault freeze frame data
- EEPROM data as log. File (see SI27.10-P-0001-01C)
- Completed analysis sheet for automatic transmission (9G- TRONIC) (maximum 2 WUs can be calculated with operation number 02- 3952 and damage code 2760B 01 for filling out the analysis sheet automatic transmission (9G- TRONIC))

### **Consultation with the Product Technical Support:**

Following consultation with Product Technical Support, repairs may be conducted on the cited parts at market launch:

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

- Radial shaft sealing rings on drive and output shafts
- Oil pan and oil filter and oil pan gasket
- Oil filter of external pressure oil filter
- Electrohydraulic controller unit
- Torque converter
- Oil pump and auxiliary oil pump
- Replace parking lock actuator, replace park pawl lift solenoid
- Replace parking lock mechanism

### **Other Work**

- Replace transmission
- Check transmission oil level, adjust to correct level, if necessary

The Shell ATF D97 (gold) Mercedes-Benz Specifications for Operating Fluids 236.16 in 1 I and 5 I containers are available as the new transmission oil for the automatic transmission (9G-TRONIC) (transmission 725.0).

### **Damage and Symptom Codes**

To encode the damage, the damage code for transmission 725.0 in design group 27 must be used, which is available as of damage code version C2013. In case of major assembly replacement, approved by Product Technical Support, the corresponding damage code based on the symptom must be used.

### Star Diagnosis Scopes / Software Update:

As of Xentry DAS version 09/2013 it is possible to flash and code the transmission control unit, to start up the electrohydraulic controller unit (EHS) and to perform standard adaptation for actuators and torque converter lockup clutch.

After replacing the transmission, torque converter and the electrohydraulic controller unit (EHS), an adaptation of actuators and torque converter lockup clutch must be performed.

### WIS

The corresponding AR documents are available in the table below (available in WIS as of DVD 09/2011). New special tools will be available at market launch.

### Introduction into Service Manual for Automatic Transmission (9G-TRONIC)

August 2013 onwards, the Introduction into Service Manual for the new automatic transmission (9G-TRONIC) (transmission 725.0) can be ordered via replacement part logistics (print 09/2013 and SD media 09/2013).

### **Parts Information**

Qty.	Part Name	Part Number
As required	Transmission oil, 1 I container	A 001 989 92 03 09
As required	Transmission oil, 5 I container	A 001 989 92 03 11
As required	Introduction into Service Manual, English	HLI 000000 1234

Analysis sheet for automatic transmission (9G- TRONIC), form		Page 7
Read out EEPROM blocks		Page 5
Filling automatic transmission with fluid	Transmission 725.0	AR27.00-P-0270EWM
Remove/install oil pump	Transmission 725.0	AR27.00-P-0400EWM
Remove/install oil pump from transmission housing	Transmission 725.0	AR27.10-P-0400- 02EWM
Remove/install transmission with torque converter	Transmission 725.0 in Model 212 with Engine 642	AR27.10-P-0500EWM
Fasten transmission on assembly stand	Transmission 725.0	AR27.10-P-0600- 01EWM
Remove/install automatic transmission oil pan	Transmission 725.0	AR27.10-P-7030EWM
Remove/install electrohydraulic controller unit (transmission installed)	Transmission 725.0	AR27.19-P-0200EWM
Remove/install torque converter	Transmission 725.0	AR27.20-P-0500
Remove/install auxiliary oil pump for automatic Transmission	Transmission 725.0	AR27.30-P-0651EWM
Remove/install radial shaft sealing ring at output flange	Transmission 725.0	AR27.40-P-0205EWM
Remove/install oil pump radial shaft sealing ring	Transmission 725.0	AR27.40-P-0300EWM
Removing and installing output flange	Transmission 725.0 in Model 212 with Engine 642	AR27.50-P-0620- 02EWM
Remove/install park pawl mechanism	Transmission 725.0	AR27.60-P-0950EWM
Remove/install lift solenoid for park pawl actuator	Transmission 725.0	AR27.60-P-0955EWM
Remove/install park pawl actuator	Transmission 725.0	AR27.60-P-0956EWM

## **Special Tools**

The following special tools are required for new automatic transmission (9G-TRONIC) (transmission 725.0):

- 725 589 00 59 00 Removal and installation tool
- 725 589 00 40 00 Support fixture
- 725 589 00 15 00 Drift
- 725 589 00 90 00 Adapter





Support fixture

### **Read Out EEPROM Blocks**

- 1. Select the "Special processes" tab (Figure 1) (1) in Xentry DAS.
- 2. Click menu item "log data" (Figure 1) (2).
- 3. Click "Start" (Figure 1) (3) to read out and save data.

	XENTRY	Diagnostics		G	) Merced	les-Ben	Z
	Diagnosis > 0	ontrol unit	,1	12.0V	Ignition		?
ŀ	👻 VGS - Tran	smission control for 9-spe	eed transmission (Y3/8n4)				
	Version Error o	codes / Events Actual values Actuations	Adaptations Control unit log Special procedures Tests				_
L	Selection		Log data				
	Log data	2	This function writes important data into a log file for the development depar The following steps are performed:	tment.			*
R	do-		<ul> <li>The control unit information is being read out.</li> <li>The fault codes are being read out.</li> <li>The event log file was written successfully.</li> </ul>				
	IPS						
			Start procedure.				
	_						-
	**	-				Continue 🕨	-
	×.		WDD2120541A000212 212.054 E (212) E: 272.952	T: 722.9	199		

#### Figure 1. Special Processes Tab, Log Data and Start.

P00.30-2057-04

4. Data is stored in the "User data range as a text file with vehicle identification number (VIN) and date (Figure 2).

		XENTRY	Diagnostic	s						Merced	es-Benz	
	ļ	Diagnosis > C	ontrol unit						12.0V	✓ Ignition		?
ŀ	-	VGS - Trans	smission cor	ntrol for 9-spe	ed transmission (Y3/8	n4)					ļ	
	1	Version Error codes / Events Actual values Actuations Adaptations Control unit log Special procedures Tests										_
L					Log data							
		Log data		A	This function writes impor The following steps are po	tant data into a erformed: ation is being re	log file for the d	evelopment departi	nent.			*
R	ç.				The fault codes are be     The event log file was	ing read out. ✓ written success	fully. ✓		h = 4) -	4		1
T	IPS				C: /star/XentryDiagnostics/va txt	r/docs/Xentry/\	/GSNAG3/WDD:	2120541A000212_	212_SXX	XXXX_VGSN	NAG3_28	
							77					4
3					•						Continue	
	ŗ.			Ŧ	WDD2120541A000212	212.054	E (212)	E: 272.952	T: 722.9	99		

### Figure 2.

P00.30-2060-05

- 5. Start STAR Utilities.
- 6. Pressing "SDexplorer" (Figure 3) (5) takes you to SDexplorer.

🖗 STAR Utilities	Ξ×
Programme Optionen Fenster Datei Bearbeiten Ansicht Format	
STAR Pad Versionsinformation StartKey Center Eigendiagnose Druckerverwalkung SDexplorer Datentransfer	
STRK-Pad Versionshronmation Startkey-Lenter Ligendagnose Unuclerverwaikung Subeport Daterriterister	

### Figure 3.

P00.30-2057-04

- The EEPROM data (Figure 4) (8) with VIN is stored in the SDexplorer under "USER\_DOCUMENTS\Xentry\VGSNAG3\" (Figure 4) (9).
- 8. To enable data to be transferred onto a data medium a "USB data medium" (Figure 4) (9) must be chosen as the storage option.
- 9. Transfer the data using "copy" (Figure 4) (10) to a USB stick. The file contains the VIN and date and time as the file name.



Figure 4.

P00.30-2058-05