
Howling from rear differential at 50-60 mph

Topic number	LI35.00-P-060851
Version	1
Design group	35.00 General
Date	02-25-2015
Validity	222 4MATIC Vehicles Produced before 10/14
Reason for change	

Complaint:

Howling or whistling from rear differential at 50 mph to 60 mph

Cause:

Gear mesh excited noise

Remedy:

Replace left rear axle shaft with part A 222 350 78 02. Part has updated damper.

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 222 350 78 02			Rear Axle Shaft	1	Left	X

Work units				
Op. no.	Operation text	Time	Damage code	Note
			35D02 36	
35-1300	REAR AXLE REMOVE/INSTALL			
35-1575				