


Model 217, 222.0/1/9
up to model year 2018




P82.60-9266-09

Shown on model 222 except for code 582 (rear air conditioning)

- 1 Armrest cover
- 2 Cover
- 3 Electrical connectors

- X39/45 AUX jack electrical connector
- X115-1 USB 1 electrical connector
- X115-2 USB electrical connector 2

	Notes on avoiding damage to optical fibers during repair work		AH82.60-P-0001-05AK
	Information on preventing damage to electronic components due to electrostatic discharge		AH54.00-P-0001-01A
	Remove/install		
1	Open armrest cover (1)		
2	Unclip cover (2) upward	Removal assembly	*000589886300
3	Release and disconnect electrical connectors (3)		
4	Release and disconnect electrical connector 1 USB (X115-1), electrical connector 2 USB (X115-2) and electrical connector AUX connection(X39/45)		
5	Remove cover (2)		
6	Install in the reverse order		



000 589 88 63 00

Removal assembly