



Model 217, 222

Shown on MODEL 222

- 1 Fender liner
- 2 Bolts
- 3 Expansion clips
- 4 Nuts



P88.10-2274-06

	Risk of death caused by vehicle slipping or toppling off of the lifting platform.	Align vehicle between vehicle lift columns and position the four support plates at the vehicle lift support points specified by the vehicle manufacturer.	AS00.00-Z-0010-01A
	Remove/install		
1	Raise vehicle with vehicle lift		
2	Remove expansion clips (3)		
3	Remove bolts (2)		
4	Unscrew bolts from fender liner on center engine compartment paneling	Model 217	AR61.20-P-1105LF
5	Unscrew nuts (4)		
6	Pull outer edge of fender liner (1) toward inside out of fender edge and remove fender liner (1) downward		
7	Install in the reverse order		