


Engine 176 in model 217, 222

Shown in model 222 without code 487
(MAGIC BODY CONTROL)

- 1 Tensioning device
- 4 Poly-V-belt
- 5 Bolts



P13.20-2158-05

Warning	Risk of injury. Skin or eye injuries may result when handling hot or glowing objects.	Wear protective gloves, protective clothing and safety glasses, if necessary.	AS00.00-Z-0002-01A
Caution	Risk of injury caused by scraping or cutting body parts on sharp vehicle parts	Always wear protective gloves when working on or near sharp and non-deburred vehicle parts. Deburr repair panels.	AS00.00-Z-0017-01A
	Remove/install		
1	Remove poly-V-belt (4) of alternator		AR13.22-P-0003MNL
2	Remove screws/bolts (5) and remove clamping device (1) downwards	Bolt, belt tensioner to right bracket	*BA13.25-P-1002-01CA
3	Install in the reverse order		

Belt tensioner

Number	Designation	Engine 176
BA13.25-P-1002-01CA	Bolt, belt tensioner to right bracket	Nm 20