

Repair Order Detail - Customer Copy

RO Number: 227190

RO Status: CLOSED

Customer: CORNEJO,STEVE

scorejo@eaglecontainerinc.com

Phone(s): Contact: (909)900-7420

Main: (909)900-7420

Cell: (909)900-7420

Vehicle: WDDNG77X08A153714

2008 S63AMG

BLACK

7ELG259

Mileage: 89,977

Payment type: VM

Waiter: No

Service advisor: 167

Promised time: 09:00 AM

Estimate: 0.00

Tag number: T3540

Promised date: 06/24/2015

~~~~~			
A	PERFORM B FLEX SERVICE AMG		
BFLEXAMG	CPM	B FLEX	328.55
		SERVICE-INCLUDES-OIL & FILTER CHANGE WITH MOBIL 1 SYNTHETIC OIL, ROTATE IF APPLIES, REPLACE CABIN DUST FILTER, BRAKE FLUID FLUSH AMG TYPE, COOLING SYSTEM CHECK, BRAKE THICKNESS/CHASSIS INSPECTION, TEST BATTERY, INSPECTION, SDS CONNECT TEST	
	Tech(s): 271		
EPA		HAZARDOUS WASTE DISPOSAL FEE	2.00
000-180-30-09		1 FILTER ELEMENT	15.75
007603-012104		1 RING,GENERAL,METAL	1.61
007603-012106		1 RING,GENERAL,METAL	1.96
001-986-80-71-17		1 WINDSHIELD WASHER FLUID	4.40
221-830-07-18		1 COMBINATION FILTER	68.25
000-989-08-07-01		1 BRAKE FLUID	20.35
000-989-83-01-USB9		9 MB GENUINE ENGINE OIL 5W-40 MB 229.	55.08

Pts: 167.40 Lbr: 328.55 Other: 2.00 Total Line A: 497.95

Story: 89980 B SERVICE **PERFORMED B SERVICE, REPLACED AC FILTERS, RENEW BRAKE FLUID. TOPPED OFF ALL FLUIDS LEVEL, CORRECT TIRES PRESSURE, FRONTS 38PSI, REARS 38PSI, SPARE 61PSI, FRONT PADS 1MM, ROTORS 34.2MM, REARS 2MM, ROTORS 24.4MM, FRONT TIRES 7MM, REARS 6MM, SHORT TEST. MIDTRONIC TEST BATTERIES JAK5A3T-9ETUPX8, P20L81T-9ETUFF8, RESET FSS, ROAD TEST, TECH 271

~~~~~			
B	CLIENT REPORTS THE CHECK BRAKE PAD WEAR LIGHT WILL COME ON.CHECK AND ADVISE		
NOTE	CP	SEE STORY	0.00
	Tech(s): 271		

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line B: 0.00

Story: 89977 **SEE LINE H, TECH 271

~~~~~			
C	CLIENT REPORTS THE AIR CONDITIONING WILL NOT TURN ON AT TIMES, THE PANEL WILL SHOW THE AIR IS ON BUT CLIENT WILL HAVE TO WAIT A		

# Repair Order Detail - Customer Copy

RO Number: 227190

RO Status: CLOSED

Customer: CORNEJO,STEVE

[scorejo@eaglecontainerinc.com](mailto:scorejo@eaglecontainerinc.com)

Phone(s): Contact: (909)900-7420

Main: (909)900-7420

Cell: (909)900-7420

Vehicle: WDDNG77X08A153714

2008 S63AMG

BLACK

7ELG259

Mileage: 89,977

Payment type: VM

Waiter: No

Service advisor: 167

Promised time: 09:00 AM

Estimate: 0.00

Tag number: T3540

Promised date: 06/24/2015

~~~~~  
 WHILE BEFORE THE AIR TURN ON,IF THE CLIENT DRIVES OVER A BUMP THE
 AIR WILL TURN ON.CHECK AND ADVISE

NOTE CP SEE STORY 518.10

Tech(s): 271

221-870-67-58 1 BLOWER REGULATOR 280.00

221-820-27-14 1 BLOWER 306.00

Pts: 586.00 Lbr: 518.10 Other: 0.00 Total Line C: 1,104.10

Story: 89980 AIR CONDITIONING DELAY BLOWING AT TIMES \*\*PERFORMED
 FUNCTION CHECK FOUND AC BLOWER DELAY AT TIMES. PERFORMED
 INSPECTION FOR LOSE CONNECTION AT BLOWER MOTOR, OK.
 PERFORMED SHORT TEST NO CODE. REMOVED AND REPLACED BLOWER
 MOTOR AS PER LI83.25-P-045617, REPLACED BLOWER REGULATOR DUE
 TO TIME. PERFORMED OPERATION CHECK FOUND AC WILL BLOWING
 NORMAL. 3.3 HRS, TECH 271

D PERFORM EDGE WORLD CLASS VEHICLE INSPECTION.

MPIE CP PERFORM EXPRESS ON 0.00

GROUND VEHICLE
 INSPECTION----INCLUDE
 S
 INSPECTING VEHICLE
 LIGHTS, TIRES AND
 EXTERIOR GLASS.

Tech(s): 271

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line D: 0.00

Story: 89980 \*\*DURING INSPECTION FOUND OIL LEAK AT RADIATOR,
 TRANSMISSION, OIL PAN AREAS. OIL DIP STICK BROKEN, OIL CAP
 LEAKING, FRONT AND REAR FLEX DISC CRACKED, BOTH FRONT LOWER
 CONTROL ARM JOINTS TORN. WINDSHIELD WASHER WILL NOT SPRAY.
 IDLER PULLEY NOISY, BELT TENSIONER WORN/JUMPING. CLIENT
 DECLINED WORK AT THIS TIME, TECH 271

E Perform California state COLD tire inflation check and correction
 as mandated by state law AB32

PSI CP Perform California 0.00

state COLD tire
 inflation check and
 correction as
 mandated by state law
 AB32

Tech(s): 271

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line E: 0.00

Story: 89980 \*\*CORRECT TIRES PRESSURE, FRONTS 38PSI, REARS
 38PSI, FRONT TIRES 7MM, REARS 6MM, TECH 271

Repair Order Detail - Customer Copy

RO Number: 227190

RO Status: CLOSED

Customer: CORNEJO,STEVE

scorejo@eaglecontainerinc.com

Phone(s): Contact: (909)900-7420

Main: (909)900-7420

Cell: (909)900-7420

Vehicle: WDDNG77X08A153714

2008 S63AMG

BLACK

7ELG259

Mileage: 89,977

Payment type: VM

Waiter: No

Service advisor: 167

Promised time: 09:00 AM

Estimate: 0.00

Tag number: T3540

Promised date: 06/24/2015

~~~~~  
 F CAR WASH  
 CW CP CAR WASH 0.00  
 Tech(s): 999  
 Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line F: 0.00  
 ~~~~~

G COURTESY LOANER CAR PROVIDED BY MB ONTARIO DURING VEHICLE
 SERVICE. \$79.95 PER DAY VALUE. NO SMOKING, CLIENT RESPONSIBLE FOR
 ANY TOLL FEES AND TO RETURN VEHICLE WITHIN 12HRS OF COMPLETED
 SERVICE UNDAMAGED TO AVOID FEES. INITIALS. \_\_\_\_\_
 LOANER CP COURTESY LOANER CAR 0.00
 PROVIDED BY MB
 ONTARIO DURING
 VEHICLE SERVICE.
 \$79.95 PER DAY VALUE.
 NO SMOKING, CLIENT
 RESPONSIBLE FOR ANY
 TOLL FEES AND TO
 RETURN VEHICLE WITHIN
 12HRS OF COMPLETED
 SERVICE UNDAMAGED TO
 AVOID FEES.
 INITIALS. \_\_\_\_\_
 Tech(s): 999
 Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line G: 0.00
 ~~~~~

H** REPLACE FRONT BRAKE PADS AS PER TECH RECOMMENDATION. CLIENT  
 DECLINED TO REPLACE ROTORS AT THIS TIME  
 TFBP CPM REPLACE FRONT BRAKE 175.00  
 PADS FOR TRUCKS AND  
 SPORT UTILITY  
 VEHICLES USING  
 GENUINE MERCEDES BENZ  
 PARTS  
 Tech(s): 271  
 004-420-75-20-41 1 TS BRAKE PAD 304.50  
 171-540-06-17 1 BRAKE WEAR SENSOR 15.23  
 01401 1 QUIET BRAKES 10.95  
 001-989-94-51-01 2 BRAKE PASTE 5.00  
 10121 1 BRAKE WASH 4.50  
 Pts: 340.18 Lbr: 175.00 Other: 0.00 Total Line H: 515.18

Story: 89977 FRONT PADS 1MM, ROTORS 33.6MM, **DURING INSPECTION  
 FOUND FRONT PADS 1MM, ROTORS 33.6MM, CLIENT ONLY APPROVED

# Repair Order Detail - Customer Copy

RO Number: 227190

RO Status: CLOSED

Customer: CORNEJO,STEVE

[scorejo@eaglecontainerinc.com](mailto:scorejo@eaglecontainerinc.com)

Phone(s): Contact: (909)900-7420

Main: (909)900-7420

Cell: (909)900-7420

Vehicle: WDDNG77X08A153714

2008 S63AMG

BLACK

7ELG259

Mileage: 89,977

Payment type: VM

Waiter: No

Service advisor: 167

Promised time: 09:00 AM

Estimate: 0.00

Tag number: T3540

Promised date: 06/24/2015

~~~~~  
 PADS, REPLACED FRONT PADS, 1.4 HRS, TECH 271
 ~~~~~

I** REPLACE REAR BRAKE PADS AS PER TECH RECOMMENDATION.CLIENT  
 DECLINED TO REPLACE ROTORS AT THIS TIME

RBP	CPM	REPLACE REAR BRAKE PADS WITH GENUINE MERCEDES BENZ PARTS	125.00
-----	-----	----------------------------------------------------------	--------

Tech(s): 271		
164-420-24-20	1 TS DISK BRAKE PAD	173.25
171-540-06-17	1 BRAKE WEAR SENSOR	15.23
01401	1 QUIET BRAKES	10.95
001-989-94-51-01	2 BRAKE PASTE	5.00
10121	1 BRAKE WASH	4.50

Pts: 208.93 Lbr: 125.00 Other: 0.00 Total Line I: 333.93

Story: 89977 REAR PADS 2MM, ROTORS 24.6MM **DURING INSPECTION  
 FOUND REAR PADS 2MM, ROTORS 24.4MM, CLIENT ONLY APPROVED  
 PADS, REPLACED REAR PADS, TECH 271

~~~~~  
 J\*\* CLIENT APPROVED TO REPLACE FRONT WIPER BLADES AS PER TECH
 RECOMMENDATION

| | | | |
|------|----|-----------|------|
| NOTE | CP | SEE STORY | 0.00 |
|------|----|-----------|------|

| | | |
|---------------|------------------|-------|
| Tech(s): 271 | | |
| 221-820-08-45 | 1 TS WIPER BLADE | 68.25 |

Pts: 68.25 Lbr: 0.00 Other: 0.00 Total Line J: 68.25

Story: 89980 WIPERS WORN \*\*DURING INSPECTION FOUND WIPERS WORN,
 REPLACED WIPERS, NO CHARGE, TECH 271

~~~~~  
 K** REVISED ESTIMATE TO \$2688.79 SPOKE TO STEVE CORNEJO ON 06/23/15  
 AT 2:31PM TO REPLACE FRONT AND REAR BRAKE PADS, BLOWER MOTOR AND  
 REGULATOR AND WIPER BLADES

REVEST	CP	REVISED ESTIMATE_____	0.00
--------	----	-----------------------	------

Tech(s): 999

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line K: 0.00

~~~~~

| | |
|---------------------------|----------|
| Customer Pay | |
| Labor | 1,146.65 |
| Parts | 1,370.76 |
| Lube | 0.00 |
| Sublet | 0.00 |
| Miscellaneous/Shop Charge | 2.00 |
| Deductible | 0.00 |

Repair Order Detail - Customer Copy

| | |
|---------------------------|----------|
| Total Charges | 2,519.41 |
| Less Insurance/Adjustment | 0.00 |
| Sales Tax | 109.66 |
| Total | 2,629.07 |