

## Vehicle maintenance report

2003 Mercedes SL500 R230

Date	Mileage	Cost
8/19/2015	104,168	\$0.00
SBC Control Unit From previous owner: Red service brake light on, Scan found code C249 active. Replaced SBC control unit \$1288.90. Previous owner had extended warranty plan which covered SBC unit. Repair performed at Southwest Auto Dallas Tx		
8/19/2015	104,168	\$0.00
Hood Switch From previous owner: Hood open warning light on. Replaced faulty switch 47.69 Repair performed at Southwest Auto Dallas Tx		
8/20/2015	104,192	\$0.00
Battery From previous owner: Install new starter battery \$195.89 Installed by Kwik Kar Willow Bend Plano Tx		
9/30/2015	104,485	\$300.00
Pre Purchase Inspection Had pre purchase inspection done by AutoScope in Dallas area.		
10/3/2015	104,500	\$12,500.00
Purchase Purchased from Lightning Motorsports in Grapevine Texas, made \$500 deposit on 9-28. Received good inspection report from AutoScope 9-30. Completed wire transfer of balance \$12,000 on 10-1, flew to Dallas on 10-3 & drove car back to Michigan.		
10/6/2015	105,811	\$0.00
Head Light Restoration Progressively sanded headlights then polished with polishing compound. Applied canuba wax for protection.		
10/6/2015	105,811	\$30.42
Air Filters Installed new intake air filters purchased from Huskers.		
10/7/2015	105,811	\$175.00
Grille Purchased single bar grille from Protech (ebay seller).		
10/7/2015	105,811	\$23.30
Differential Fluid Change Drained Diff and refilled with Mobil 1 75w90 gear oil. Used more than 1 1/2 quarts		
10/7/2015	105,811	\$37.00
Oil Change Drained crank case and refilled with 8 Quarts of Mobil 1 -W40(had 3 Quarts in stock). Installed new fleece filter with new o-rings. Reset FSS, Service "A" due in 10,000 miles.		
Walmart 5 quarts Mobil 1 \$27.00 Huskers MB MB oil filter \$10.00		
10/8/2015	105,817	\$0.00
Glove Box Repair Glove box door catch would not release. Removed glove box, cleaned and freed up latching mechanism. Reinstalled glove box as needed.		

## Vehicle maintenance report

2003 Mercedes SL500 R230

Date	Mileage	Cost
10/8/2015	105,817	\$42.12
Cabin Micro Filter Remove lower passenger side under dash cover. R & I filter set purchased from Huskers.		
10/10/2015	105,890	\$0.00
Steering Rack and Pinion Flush Removed main line on steering rack, drained reservoir,refilled with Pentosin CHF11s. Ran motor and repeated drain fill cycle. Used fluid from ABC fluid purchase. Used approx 2 liters.		
10/10/2015	105,890	\$143.13
ABC Fluid Flush with filter Purchased 10 liters Pentosin CHF11s from ECS Tuning, flushed system. Used more 7 Liters. Installed new filter purchased from Huskers.		
ECS Tuning 10L Pentosin CHF 11S \$112.71 Huskers MB Filter element \$ 30.42		
10/14/2015	106,005	\$48.86
Antenna Antenna base was broken from Previous owner. Purchased base from ECS Tuning at huge discount unpainted. Purchased aerosol paint Brilliant Silver code 744 from ebay seller The Touchup Store. Painted base, R&I as needed.		
ECS Tuning Base \$15.88 The Touchup Store \$32.98		
10/22/2015	106,144	\$149.02
Belt Tensioner/Idler Pulley As part of "B" service, replaced belt tensioner and upper right idler pulley.		
Belt Tensioner AutohausAZ \$122.69 Idler Pulley Huskers \$ 26.33		
10/22/2015	106,144	\$82.88
Spark Plugs Replaced all 16 Spark plugs with new Bosch 7422 purchased from AutohausAZ. \$5.18 each		
10/23/2015	106,155	\$149.31
Pulsation Damper Droning noise coming from the ABC system at lower RPM's. Recommended solution by MB to replace pulsation damper ie nitrogen sphere attached to pressure control valve. R&I Damper as needed which corrected droning sound.		
Huskers MB Damper \$138.06 Shipping \$ 11.25		
10/26/2015	106,226	\$31.59
Serpentine Belt Replaced belt as part of "B" Service		
10/26/2015	106,226	\$28.28
Wipers R&I wipers as needed. Bosch Wipers purchased from Amazon seller.		
10/28/2015	106,275	\$21.00
Head Light Restoration Headlights still appeared not clear. Refinished using Sylvania Restoration Kit purchased from Advance		

## Vehicle maintenance report

2003 Mercedes SL500 R230

Date	Mileage	Cost
Auto		
11/15/2015	106,656	\$80.28
Seat Lumbar Support Drivers seat lumbar support was leaking air and not inflating. Removed seat back and installed new air bladder as needed, purchased from Huskers.		
Bladder ass'y	69.03	
Shipping	11.25	
11/28/2015	106,863	\$36.99
Car Cover Purchased car cover from Xtreme Cover Pro to cover car for winter storage.		
12/23/2015	107,320	\$34.15
Transmission Service Parked car for winter, trans leaking at pan. Dropped pan, cleaned and replaced filter, pan gasket and drain plug. Had to drill out old drain plug on bench. Parts purchased at Rochester Hills MB		
Gasket	\$16.00	
Filter	\$12.50	
Seal Ring	\$ 1.90	
Drain Plug	\$ 1.82	
12/29/2015	107,320	\$16.43
Transmission Adapter Plug Transmission leaking fluid. Found TCM adapter plug oily. R&R as needed. Part purchased from Rochester Hills MB		
15.50 + tax 0.93		
1/7/2016	107,320	\$68.00
Oil Change Accidently mixed ATF with engine oil. Drained and refilled with 8 Quarts Mobil 1 0-W40 plus new filter.		
2 Jugs Mobil1 Walmart	58.00	
1 Filter Huskers	10.00	
1/7/2016	107,320	\$149.04
Transmission Flush Purchased 14 liters of Fuchs 4134 ATF from Pelican Parts and flushed through sytem 3 Liters at a time per WIS. Adjusted level at 80C.		
3/29/2016	107,320	\$214.50
Accumulator Replaced front and rear accumulators to improve ride quality Front accumulator appeared ok, rear accumulator was blown and full of fluid. Purchased Corteco accumulators from Pelican with \$25 off (full price \$239.50)		
4/22/2016	108,150	\$51.26
Ball Joint Found left front lower ball joint boot torn. R&R both left and right joints as needed. Lemfoerder parts purchased from All European Parts in Royal Oak.		
Ball Joint 25.63 ea x 2 = 51.26		

## Vehicle maintenance report

2003 Mercedes SL500 R230

Date	Mileage	Cost
4/23/2016	108,150	\$95.22
Motor Mount Vibration from the motor could be felt though out the car. R&R both front left and right mounts. Found both leaking oil and had collapsed. Also replace rear motor mount on transmission which was also collapsed.  Lemfoerder parts purchased from FCP Euro  Front mounts 36.11 ea x2 = 72.22 Rear mount 23.00 ea = 23.00		
5/4/2016	108,360	\$490.65
Tires Two rear tires installed at Rey's Tire & Auto Center Utica, Continental DWS Extreme Contact 285/35R18. Road Force balance.		
8/23/2016	112,047	\$177.56
Rear Brakes Installed new ATE rotors and Akebono pads  Rotors FCP Euro 60.11ea =120.22 Pads Amazon 57.34		
9/23/2016	112,951	\$27.55
ABC Valve Block R&I front suspension valve block with new o-rings. Installed o-rings purchased from Orings and More Buna N 90 compound.		
<b>Total Cost</b>		<b>\$15,203.54</b>