

12/2014 [2014-10-29] - Developer Mode - AddOns: ..., 4147,4152,4153,4154,4157,4170,4115,4118,4133,4162,4158,4167,4140,4163 VIN : WDBSK75F73F006094 Battery voltage: 12.1 V

Vehicle **230.475** Control unit **ME-SFI 2.8**

Fault codes

Code	Text	Status
P20E2	Unauthorized ambient condition for SBC request for idle speed increase (P1999)	STORED
P20B7-008	Increased idle speed due to SBC low-voltage : Check current and voltage on vehicle. / No control module defective (P1999)	STORED
P2017-001	Self-adaptation of mixture formation for right bank of cylinders is at limit value (at idle speed). Enrichment over permissible limit (P0171)	Current and stored
P2086-001	Self-adaptation of mixture formation for left bank of cylinders is at limit value (at idle speed). : Enrichment over permissible limit (P0174)	Current and stored

ESC F1 F3 F5 F6 F8 F9 F11